Form 3160-5 (July 1989) (Formerly 9-331)

UN ED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

CONTACT RECEI® 7
OFFICE FOR NUME
OF COPIES REQUIRED
(Other instructions on reverse side)

BLM Roswell District Modified Form No. NM060-3160-4

5. LEASE DESIGNATION AND SERIAL NO.

DOTTE ACT	JI CAND MANACINENT		LC-028//5-B	j.	
(Do not use this form for proposals	ES AND REPORTS ON to drill or to deepen or plug back to	a different raserypir. DD		TEE OR TRIBE NAME	
USE "APPLICATION	FOR PERMIT-" for such proposals.)	Artosia, NM 8	82 10		
1. OIL GAS CTHER WIW			7. UNIT AGREEMENT	7. UNIT AGREEMENT NAME	
				Robinson Jackson Unit	
2. NAME OF OPERATOR				8. FARM OR LEASE NAME	
Southland Royalty Company -	<u></u>		RJU Tract 2		
3. ADDRESS OF OPERATOR 3a. AREA CODE & PHONE NO.			9. WELL NO.	9. WELL NO.	
P.O. Box 51810, Midland, TX 79710-1810 (915)688-6800			17		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*			10. FIELD AND POOL, OR WILDCAT		
See also space 17 below.) At surface		0.000	Grayburg Jackson 7R,QN		
1980' FSL & 1980' FWL	9 1995	11. SEC., T., R., M., OR BLK. AND			
			SURVEY OR AREA		
		Colon D.	Sec35, 17S,	29E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF,		12. COUNTY OR PARIS		
	3542' GL		Eddy	NM	
16. Check An	<u> </u>	Nictions of Nicking Day			
Oneck App	propriate Box To Indicate	nature of notice, Repo	ort, or Other Dat	а	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
TEST WATER SHUT-OFF P	ULL OR ALTER CASING				
		WATER SHUT-OFF	REPAIRING	├	
	BANDON* X	FRACTURE TREATMENT	ALTERING	— —	
	HANGE PLANS	SHOOTING OR ACIDIZING	ABANDONN	AENT-	
(Other)	PANGE PLANS	(Other)	of multiple completion	on Well	
		Completion or Recor	npletion Report and Log	form.)	
 DESCRIBE PROPOSED OR COMPLETED OPE posed work. If well is directionally work.)* 	drilled, give subsurface locations and	alls, and give pertinent dates, in measured and true vertical depti	cluding estimated date ones for all markers and z	ones pertinent to this	
MIRU Release packers. POH.	RIH w/2 7/8" tubing, bit ar	nd scraper to 3130'.			
RIH w/7"-20# CICR and set @ 3 interval w/50 sxs Class C. Pugelled brine. RIH w/7" CIBP and set @ 2490'	ull out of retainer and dump	o 6 sxs Class C atop sa	/burg Jackson op ame. Displace ho	en hole le w/10ppg	
RIH w/4" casing gun and perfo 1000 psi. Cement w/30sxs C	prate from 900'-901' w/4J lass C below retainer. Dro	IHPF. RIH w/7" CICR an p 6 sxs Class C atop s	d set @ 850'. Te ame.	st tubing to	
RIH w/4" casing gun and perfo	orate 550'-551' w/4 JHPF.	•			
Establish circulation down 7" of and circulate to surface.	casing. Displace hole w/fr	esh water. Mix and pu	ımp 150 sxs Clas	s C cement	
Cut off casing 3' below surface and place abandonment maker as per regulations			ons.	<u> </u>	
Restore location as directed.					
				<u></u>	
				(Y) < (Y)	
\sim				were and the second	
8. I hereby certify that the foregoing is tru	e and correct		<u> </u>	<u> </u>	
	PROI	DUCTION ASSISTANT	6/	22/93	
SIGNED	TITLE		DATE	·	
(This space for Federal or State office u	ise)				
APPROVED BY FORIG. SCOO DA	VID R. GLASS		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
APPROVED BY CONDITIONS OF APPROVAL. IF ANY:	THE T		DATE	<u> </u>	
- ,	Δ				
SEE ATTACHE	${\cal V}$				

*See Instructions on Reverse Side