

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIPT
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on reverse
side)

BLM Roswell District
Modified Form No.
NM060-3160-4

45F

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER WIW		5. LEASE DESIGNATION AND SERIAL NO. LC-028775-B	
2. NAME OF OPERATOR Southland Royalty Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 51810, Midland, TX 79710-1810		7. UNIT AGREEMENT NAME	
3a. AREA CODE & PHONE NO. 915-688-6898		8. FARM OR LEASE NAME RJU Tr.2 A	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface G, 1980'FNL & 1980' FEL		9. WELL NO. 6	
10. FIELD AND POOL, OR WILDCAT Grayburg Jackson SR-QN-G		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 35, T17S, R29E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3563' GR.	12. COUNTY OR PARISH Eddy	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
ABANDON*	<input checked="" type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

RIH w/Cmt retainer for 7" 20# csg on a 2-7/8" 6.5# N-80 workstring and set at 3020'. Test tbg to 1000 psi. Establish injection rate with fresh water. Squeeze below retainer with 50 sx of CI C cmt. Pull out of retainer and dump 6 sx CI C cmt on top of retainer. Circ hole with 10 ppg gelled mud. POH. RIH w/CIBP for 7" 20# casing on the 2-7/8" workstring and set at 2480'. Dump 20 sx CI C cmt on CIBP. POH.

RIH with 4" csg gun and perf 850' - 851' with 4 spf (8 holes). POH. RIH with a cmt retainer for 7" 20# casing on the 2-7/8" workstring and set @ 750'. Test tbg to 1000 psi. Establish injection rate with fresh water. Squeeze below retainer with 25 sx CI C cmt. Pull out of retainer and dump 6 sx CI C cmt on top of retainer. POH.

RIH with 4" csg gun and perf 515' - 516' with 4 spf (8 holes). POH. ND BOP. Pump fresh water down the 7" csg to establish circulation. Pump 130 sx CI C cmt and circ to surface. Cut off casing 3' below surface and weld on steel plate. Set abandonment marker. Restore location.

18. I hereby certify that the foregoing is true and correct.

SIGNED		TITLE	Reg. Compliance Rep.	DATE	12/10/91
(This space for Federal or State office use)					
APPROVED BY		TITLE	PARTIAL FOR INDIAN	DATE	2/3/92
CONDITIONS OF APPROVAL, IF ANY:					

*See Instructions on Reverse Side

MERIDIAN OIL

JMS 12/10/91

RJU TR 2A No. 6
GBG JACKSON 7RV QN SA FIELD
EDDY COUNTY, NEW MEXICO

CURRENT CONDITION

