Form 9-331 (May 1963) 	DEPARTMENT	N.M.O.C.D. STATES OF THE INTERIO GICAL SURVEY AND REPORTS O ill or to deepen or plug ba of person successor	DR verse	MIT IN TRIPLIC. er instructions on side) LLS	5. LEASE	DESIGNATION	red. Sau No. 42-RI AND SERIAL	NO.
1. OIL GAS WELL WEL 2. NAME OF OPERATOR	L OTHER	,	NOV	5 1979	8. FARM	AGREEMENT N OR LEASE NA	ME	
 ADDRESS OF OPERA Box #198 LOCATION OF WELL See also space 17 At surface 	3, Artesia, New M	exico 88210 d in accordance with any S	state requi		9. WELL 10. FIEL Squa: 11. SEC. SEC.	4 re Lake , T., R., M., OR URVEY OR ARE 1-175-3	OR WILDCAT GBG, S, BLR, AND A	
14. PERMIT NO.		EVATIONS (Show whether DF,		·	Ede	dy	H 13. STATE New M	<u>lexi</u> co
16.	Check Approprie	ate Box To Indicate No :	JUIE OF		SEQUENT REPO			
TEST WATER SHO FRACTURE TREAT SHOOT OR ACIDIZ REPAIR WELL (Other)	MULTIPLI		FRA SH(TER SHUT-OFF ACTURE TREATMENT OOTING OR ACIDIZING ther) (NoTE: Report res Completion or Reco	ults of multip mpletion Rep	REPAIRING ALTERING ABANDONM ole completion ort and Log f	CASING	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

See attached sheet.

.

RECEIVED

NOV	1	1979
-----	---	------

U.S. GEULUGICAL SURVEY ARTESIA, NEW MEXICO

18. I hereby certificate the foregoing is true and correct SIGNED May	TITLE Consulting Engineer	DATE Oct. 31, 1979
(This space for Federal or State office use) (Chg. Sgd.) GEORGE H. STEWART APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	ACTING DISTRICT ENGINEER	GOT 0 1 1973 DATE

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Fed-eral and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any Starc, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions. Item 17: Proposals to abandom a well and subsequent reports of abandomment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandomment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site or different and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandomment.



WINDFOHR OIL COMPANY Jackson "B" #4

Found tubing stuck at 2725. Shot off and recovered. Washed over fish at 2625'. At 2724' hit water flow (1500 BPD). At 2727' picked up additional 1,000 BWPD. Drilled gyp to 2800'. On Aug. 4, 1979, flowed 2,570 BWPD and this decreased to 1,715 BPD on Aug. 8. Cleaned out with wash pipe to 2963'. Pulled pipe and recovered 6 joints of tubing and 3 joints of anchor. Cleaned out with bit to 3450', total depth. Ran gamma ray-neutron and caliper logs. Ran Lynes packer to 2695' on Aug. 16. Pressured casing to 1,000 psi. Pressure held. Lowered packer to 2,735'. Wouldn't set. Pulled packer. Ran Lynes packer and set at 2736'. Water flow below packer was 400 BPD. Lowered packer to 2745'. Water shut off below. Reset packer at 2716'. Water flow below packer back to 1,645 BPD. Pulled packer. On Aug. 28, 1979, ran $4\frac{1}{2}$ " O.D. 9.5# J-55 casing with Lynes packer on bottom. Set packer at 2795'. Cemented above packer with 500 sacks class H cement with .3% CFR-2 and 6# salt/sx. Circulated cement when had 45 bbls. left. Shut-in bradenhead and squeezed with 225 sacks cement at 1400 psi. on $4\frac{1}{2}$ ".

On Sept. 4, 1979, drilled out DV tool, float shoe and 5' of cement. Drilled cement and formation to 2815'. Drilled formation from 2815 to 2852'. Ran deviation tests as follows:

DEPTH	DEGREES OFF VERTICAL
2700	1.10
2740	1.50
2800	1.90
2845	2.5 ⁰

Ran cement bond and caliper logs. On Aug. 11, 1979 resumed drilling. Drilled new hole to 3001'. On Sept. 17 acidized with 750 gals. 15% Mattrix acid. Swabbed acid and water. On Sept. 20, 1979, ran Lynes packer and set at 2831'. Pumped in water, but communicated. Raised packer into $4\frac{1}{2}$ " casing. Acidized open hole with 1,500 gallons 15% acid at 2.9 BPM and 1800 psi. Swabbed acid and water. Fluid entering at rate of 1 BP hour. Installed pumping equipment. Resumed producing on Sept. 25, 1979.