STATE OF NEW MEXICO	-	<i>*</i>			
ENERGY AND MINERALS DEPARTMEN					
NO. OF COPIED RECEIVED		ATION DIVISI		F . A 1 A	
DISTRIBUTION		IOX 2088 RECEIVED L	JY	Form C-101 Revised 10	
SANTA FE	SANTA FE, NE	SANTA FE, NEW MEXICO 87501			
FILE VV		MAY 20198	5 Sa. Indicate Ty	rpe of Lease	
V.S.G.S.			State K	Fee	
LAND OFFICE		0. C. D.	5. State Off 6	Gas Lease No.	
OFERATOR		ARTEBIA, CONT		2130	
DO NOT USE THIS FORM FOR PROFE USE "APPLICATIO	NOTICES AND REPORTS C	G BACK TO A DIFFERENT RESERVOIR.			
1. OIL 6A3	Burnhan San And	7. Unit Agreement Name Burnham Grayburg San Andres Unit			
2. Name of Operator		8. Farm of Lease Name			
Anadarko Production Company V				Tract No. 1	
3. Address of Operator				9, Well No.	
P. O. Drawer 130, Arte		1			
4. Location of Well		10. Field and Pool, or Wildcat			
UNIT LETTER	980 FEET FROM THE North	1 1980	CET FROM Graybus	Lake ⁻ .g-San Andres	
THE WEST LINE, SECTION	2 TOWNSHIP	ANGE JUE	— ^{имрм.} ()))))		
	12, County	XIIIIII			
	Eddy				
16. Check A NOTICE OF IN	ppropriate Box To Indicate	•	t o r Other Data EQUENT REPORT O	F:	
	r		-	<u> </u>	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		TERING CASING	
TEMPORARILY ABANDON	_	COMMENCE DRILLING OPHS.	<u>ال</u> ۹۱،	IG AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	\Box		
		OTHER			
OTHER Restore Casing	Integrity 2	X			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

<u>Note</u>: Anadarko pressure tested the 7" production casing in this well on 5-16-85 and it would not hold pressure. We are currently uncertain of what steps need to be taken to repair and thus restore the integrity of the casing on this water injection well but plan to proceed as follows:

- 1. Rig up pulling unit.
- 2. Unset injection packer and start pulling 2-3/8" tubing out of well.
- 3. Occasionally reset packer & pressure test the casing/tubing annulus until a hole (or top of numerous holes) is located.
- 4. Determine extent of hole (holes) by using packer & RBP or casing inspection log.
- 5. Cement squeeze hole (holes) after consulting with NMOCD and gaining their approval of our cementing procedure.
- 6. Drill out cement.
- 7. Re-run plastic lined tubing; circulate chemical water in casing/tubing annulus; re-set injection packer.
- 8. Pressure test casing/tubing annulus after notifying NMOCD witness to be on location.
- 9. Return well to injection if approved.

18. I hereby certify that the In	formation above is true and complet.	e to the bes			V 17 1005
SIGNED	fuckles_	TITLE	Area Supervisor	DATE	<u>May 17, 1985</u>
APPROVED BY	ORIGINAL SIGNED BY LARRY BROOKS GEOLOGIST - NMOCD	TITLE		DATE	MAY 22 1985
	n an				