

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION
RECEIVED

OCT 9 1973

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p> <p>5. State Oil & Gas Lease No. B-2130</p>
<p>1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Injection Well</p> <p>2. Name of Operator Anadarko Production Company</p> <p>3. Address of Operator P. O. Box 67, Loco Hills, New Mexico 88255</p> <p>4. Location of Well UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM East LINE, SECTION 2 TOWNSHIP 17S RANGE 30E NMPM.</p>	<p>7. Unit Agreement Name Burnham GSA Unit</p> <p>8. Farm or Lease Name Tract No. 1</p> <p>9. Well No. 3</p> <p>10. Field and Pool, or Wildcat Square Lake</p>	
<p>15. Elevation (Show whether DF, RT, GR, etc.) 3755 GL</p>	<p>12. County Eddy</p>	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER Convert to water Injection. <input type="checkbox"/>		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up well servicing unit.
2. Pull tubing and rods.
3. Run 2 3/8" tubing with 4 1/2" tension packer.
4. Circulate water laden with corrosion inhibitor and bactericide back to the surface in the annulus.
5. Set packer at 2850' to inject through perfs 2910-18 (Metex), 3008-18 (Premier), & 3168-76 (Lovington).
6. Place pressure guage on casing annulus.
7. Place well on injection under N. M. O. C. C. Order No. R-4610.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. A. Gressett TITLE Area Supervisor DATE October 4, 1973

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE OCT 9 1973

CONDITIONS OF APPROVAL, IF ANY: