Form 3160-5 (June 1990)

## UNITED STATES N.M. Oil Cons. Division DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEME 811 S. 1st Street

Artesia. NM 88210-2834

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No. NM0384575

CHARDY NOTICE	AND BEDORTO ON WHELE	INIVIO304373
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  Use "APPLICATION FOR PERMIT-" for such proposals		6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
. Type of Well		
Oll Gas Well Well Other  2. Name of Operator		8. Well Name and No.
		Dale H Parke B Tr B , #1
Premier Oil & Gas, INc.		9. API Well No.
Address and Telephone No. P.O. Box 1246, Artesia, NM 88210		30-015-04157
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit M: 330' FSL & 330' FNL FW L		10. Fleid and Pool, or Exploratory Area
		Gray burg - Jackson SR,Q,GB,SA
Sec 15 T-17S R- 30E		11. County or Parish, State
		Eddy
2. CHECK APPROPRIATE BOX(s	) TO INDICATE NATURE OF NOTICE, REPORT, O	R OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
073	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
Final Abandonment Notice	Casing Repair	Water Shut-Off
M Chapt Alamadamus and Nickley		Conversion to Injection
Final Abandonment Notice	Altering Casing	
3. Describe Proposed or Completed Operations (Clearly st directionally drilled, give subsurface locations and meas 1. 4-13-2000 MIRU first call 2. 4-14-2000 POH w/ tubing set 4 1/2 CIBF	Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  of starting any proposed work, if well is work.)*
3. Describe Proposed or Completed Operations (Clearly statistic directionally drilled, give subsurface locations and measured to the control of the control	Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  of starting any proposed work. If well is work.)*
3. Describe Proposed or Completed Operations (Clearly staticectionally drilled, give subsurface locations and meast 1. 4-13-2000 MIRU first call 2. 4-14-2000 POH w/ tubing set 4 1/2 CIBF 3. 4-14-2000 RIH circulate well w/9.8 mud 4. 4-14-2000 spot 25sx. class "C" neat cmt 5. 4-17-2000 cut 7 " cassing @1325' could 6. 4-18-2000 RIH spot 25 sx. class "C" neat 7. 4-18-2000 cut 7" @ 1021 couldn't pull 0. 8. 4-18-2000 RIH spot 25 sx. class "C" neat 9. 4-19-2000 RIH spot 25 sx. class "C" neat cmt 10. 4-19-2000 spot 30 sx. class "C" neat cmt 11. 4-19-2000 spot 10sx class "C" neat cmt 12. 4-20-2000 cut off well head install dry hold the static stat	tate all pertinet details, and give pertinent dates, including estimated date of sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and zones pertinent dates.  The sured and true vertical depths for all markders and zones pertinent to this will be a sured and zon	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  of starting any proposed work. If well is work.)*
3. Describe Proposed or Completed Operations (Clearly staticectionally drilled, give subsurface locations and measured in the subsurface location in the subsurface location is discussed in the subsurface location in the	Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  of starting any proposed work. If well is work.)*
13. Describe Proposed or Completed Operations (Clearly static directionally drilled, give subsurface locations and measured in the subsurface of the subsurface locations and measured in the subsurface	tate all pertinet details, and give pertinent dates, including estimated date of sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and true vertical depths for all markders and zones pertinent to this will be a sured and zones pertinent dates.  The sured and true vertical depths for all markders and zones pertinent to this will be a sured and zon	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  of starting any proposed work. If well is work.)*  PR 20 A P

## NEOEIVEO