

## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELL

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	X
REPORT ON RESULT OF PLUGGING OF WELL	X		

I

OIL CONSERVATION COMMISSION, **Artesia, New Mexico** Place Date  
 Santa Fe, New Mexico **December 7, 1948**

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the \_\_\_\_\_

~~Yancey-Harris Company~~ **Etz-State (Humble)** Well No. **5A** in the  
 of Sec. **16** T. **17** R. **30**, N. M. P. M.,  
**Grayburg-Jackson** Field, **Eddy** County

The dates of this work were as follows: **December 1st to December 7th, 1948**

Notice of intention to do the work was (was ~~XXXXX~~ submitted on Form C-102 on **December 1** 19 **48**  
 and approval of the proposed plan was (was ~~XXXXX~~ obtained. (Cross out incorrect words.)

## DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Filled hole with mud to 3100 feet and dumped in 5 sacks; filled with mud to 2140 feet and dumped in 10 sacks; filled with mud to 1840 feet and dumped in 5 sacks; filled with mud to 460 feet and dumped in 5 sacks; filled with mud to surface and set regulation marker (4' pipe above ground, not less than 4" in diameter, and cemented in; filled cellar and pits. Pulled 2150' ~~XXXXX~~ of 5 1/2", 502' of 7" OD, and 170' of 8 1/4". Cleared location of junk.

Witnessed by \_\_\_\_\_

Name

Company

Title

Subscribed and sworn to before me this **16th**day of **December** **1948**

*Morris H. Sanlier*  
 Notary Public

My Commission expires **June 26, 1951**

I hereby swear or affirm that the information given above is true and correct.

Name

Position

Representing

**Yancey-Harris Company**  
 Company or Operator

Address

**P.O. Box 308, Artesia, N. Mex.**

Remarks:

Name

Title