

m. 3100-5
November 1983)
formerly 1-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIE
(Other Instructions
verse side)

BLM Form No. 1004-11-1
Expires April 31, 1-85

CLSF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

1. NAME OF OPERATOR

Phillips Petroleum Company

2. ADDRESS OF OPERATOR

4001 Penbrook Street, Odessa, Texas 79762

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit H, 1345' FNL & 1295' FEL

14. PERMIT NO.

API No. 30-015-04192

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3637' GL

5. LEASE DESIGNATION AND SERIAL NO.

LC-028793-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Burch "AA" Federal

9. WELL NO.

22

10. FIELD AND POOL, OR WILDCAT

Gb/Jackson/SR-Q-Gb-SA

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 19, 5-17-S, R-30-E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) Set CIBP above producing

Interval and TA Wellbore

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

X

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. If state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.*

2-11-92 RU. DDU GIH w/5-1/2 scraper on workstring. Pumped 60 bbls hot water down casing. Continue in hole with scraper to 2410. POOH standing workstring back.

2-12-92 RU, GIH w/7" CIBP set at 2335', COOH with wireline. GIH w/ bailer on wireline, dump 35' cement over CIBP. COOH with wireline. GIH with workstring to 2280' circulate wellbore, close BOP. Pressure test to 500 psi for 15 min. No leakage. Mr. Don Early from BLM witness test. Pulled workstring and BOP. Complete Drop from report. Request permit to TA well for 1 year.

This Approval of Temporary
Abandonment Expires

APPROVED FOR 12 MONTH PERIOD

ENDING 2/12/93

2/12/97-G.W.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Supervisor Reg/Proration

DATE 2-14-92

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

