

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Co. Division
811 S. 1st Street
Artesia, NM 88210-2834

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

CISF

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

Oil Well Gas Well Other

2. Name of Operator

Marbob Energy Corporation

3. Address and Telephone No.

P.O. Drawer 227, Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990 FSL, 1650 FWL, Sec. 19, T17S, R 30E, Unit N

5. Lease Designation and Serial No.
Lc-028784B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Burch Keely Unit #103

9. API Well No.

30-015-04206

10. Field and Pool, or Exploratory Area

Grbg Jackson Sr Q Grbg Sa

11. County or Parish, State

Eddy County, NM

RECEIVED
OCD ARTESIA
MAR 21 1993

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Notify BLM 24 hrs. before starting

1. POH w/ rods & tubing
2. RHH spot 100' plug @ 2520' (perf 2504 to 3570) woc 900'
3. Perf. 7" casing @ 840' sqz 100' plug (base salt 788') woc TAG
4. Perf 7" casing @ 515' sqz 225' cmt (8 1/4 shoe 464, top salt 385') TAG
5. Perf 7" casing @ 60' circulate cmt to surface 436
6. cut off well head install dry hole marker

* ***Set CIBP within 50 to 100 feet above the open perforations and cap with 35 feet of cement; or
***Set a cement plug which extends to a minimum of 50 feet below to 50 feet above the perforated interval.
TAG

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct

Signed *Alexis C. Swoboda*

Title *Agent*

Date 3-27-01

(This space for Federal or State office use)

(ORIG. SGD.) ALEXIS C. SWOBODA

Title PETROLEUM ENGINEER

Date APR 13 2001

Approved by _____
Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side