

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM 10-1 (10-1)
(Other Instructions on Reverse Side)

Expires August 31, 1985

3. LEASE DESIGNATION AND SERIAL NO.

LC-028793-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Burch AA Fed

9. WELL NO.

25

10. FIELD AND POOL, OR WILDCAT

Gb/Jackson SR-Q-Gb-SA

11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA

Sec. 19, 17-S, 30-E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Phillips Petroleum Company

3. ADDRESS OF OPERATOR

4001 Penbrook Street, Odessa, Texas 79762

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

Unit I, 2615' FSL, 1295 FEL

14. PERMIT NO.

API No. 30-015-04209

15. ELEVATIONS (Show whether DF, ST, OR, etc.)

3630' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Set CIBP above producing

Interval and T.A. Wellbore

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1-28-92 GIH with 2-3/8" workstring. Land at 2450, COOH.
1-29-92 GIH with 7" gauge ring to 2500', COOH. GIH with 7" CIBP and set at 2475', COOH. GIH with dump bailer and dump 7 sacks of cement, appx. 35' of cement in 7" casing. GIH with workstring and land at 2435'. Load hole and pressure casing to 520#, with 95 Bbls inhibited fluid. Integrity test passed. Don Early with BLM witnessed casing integrity test. Layed down workstring. Wellbore TA. Complete Drop from Report. Request permit to T & A for 1 Year.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Supervisor Reg/Proration

DATE 2-4-92

(This space for Federal or State office use)

(915) 368-1488

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED FOR 12 MONTH PERIOD

DATE 3/1/93

*See Instructions on Reverse Side

535

