F	orm	9-331	
t	May	1963	}

16.

## DEPARTMENT .

1 I LJ	101 1010 12 111 210 11 10	
HE INTERIOR	(Other instructions verse mide)	or

GEOLOGICAL SURVEY

CHNDRY	NOTICES	AND	<b>REPORTS</b>	ON	WELLS
ALIIVIJK I	INCHICES	AINU	NEI ONIS	$\mathbf{v}_{1}$	**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT-" for such proposals.)

	7
OIL X GAB WELL OTHER	
General American Oil Company of Texas	
P. O. Box 128, Loco Hills, New Mexico 88255	3
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface	1

660' FSL and 660' FEL

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. 3618' DF

Form approved, Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND BERIAL NO.

LC-028793-C
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

RE . UNIT AUREEMENT NAME

S. FARM OR LEABER TO	7	, ,	7	 
Burch C				 

· 487.33 #5 O. FIELD AND POOL, OR WILDCAT

Grayburg Jackson 11. MRC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 19, T-17-S, R-30-E 12. COUNTY OR PARISH | 13. STATE

New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF Х FRACTURE TREAT  $\mathbf{X}$ SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON<sup>4</sup> CHANGE PLANS

SUBHEQUENT REPORT OF: WATER SHUT-OFF PRACTURE TREATMENT SHOOTING OR ACIDIZING

REPAIRING WELL ALTERING CARING ABANDON MENT®

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

## We Propose To:

(Other)

Dig small workover pit. Pull rods and tubing. 1.

Set retrievable bridge plug above current producing zone. 2.

Log, perforate and cement across Seven Rivers. 3.

4. Drill out cement.

Log and perforate Seven Rivers and Loco Hills zones. 5.

Sand frac Seven Rivers and Loco Hills zones and test.

Retrieve retrievable bridge plug and return well to production.

RECEIVED	
	)
U.S. GLULUGICAL SURVEY  ARTESIA, NEW MEXICO	

<sup>18.</sup> I hereby certify that the foregoing is true and correct Asst. Field Superintendent DATE November 12, TITLE \_\_ (This space for Federal or State office use) TITLE DATE APPROVED BY CONDITIONS OF APPROVAL, IF ANY: