OF THE PRINCE

		MM OIL CONS. COMM	ITabaon
(June 1990) DEPARTM	UNITED STATES MENT OF THE INTERIOR	Drawer DD Artesie MM 8821	Expires: March 31, 1993
BUREAU C	OF LAND MANAGEMENT		5. Lease Designation and Serial No.
SUNDRY NOTICE	ES AND REPORTS ON W	ELLS	NM LC-029342-E  6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to			
	FOR PERMIT—" for such pre		N/A
01104	UT IN TOID IOATE		7. If Unit or CA, Agreement Designation
1. Type of Well	MIT IN TRIPLICATE		
Gas G			N/A  8. Well Name and No.
2. Name of Operator		1997	<u>`</u>
Southwest Royalties, Inc.		£45	Dexter E Federal #2
3. Address and Telephone No.		C. f. D	30-015-04230
c/o Box 953, Midland, Te	xas 79702 (915) 68	34-6381	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Surve			Grayburg-Jackson-SR-Q
Unit G, 1650 FNL & 2310 FE	L Sec. 20, T-17	'-S, R-30-E	11. County or Parish, State G-S
			Eddy County, N.M.
12. CHECK APPROPRIATE BO	X(s) TO INDICATE NATU	RE OF NOTICE, REPO	ORT, OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTION	N ·
X Notice of Intent	Abandonmer	nt	Change of Plans
	Recompletion	n	New Construction
Subsequent Report	Plugging Ba	ck	Non-Routine Fracturing
	Casing Repa	ir	Water Shut-Off
Final Abandonment Notice	Altering Cas		Conversion to Injection
	X Other Mec	hanical Integrity Test	(Note: Report results of multiple completion on Well
13. Describe Proposed or Completed Operations (Clearly sta	te all pertinent details, and give pertinent da	tes including estimated date of start	Completion or Recompletion Report and Log form.)
Procedure and	dure for testing down wellbore diagram atta 05) 887-6544 - 48 hou	ched.	
14. I hereby certify that the foregoing is the houlforrect  Signed  Aut 1	Dog1		7 12 02
(This space for Federal or State office use)	Title Kegula	itory Agent	Date
(Init space for Pederal of State office use)  (ORIG. SGD.) DAVID R.  Approved by Conditions of approval, if any:	GLASS Title		Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

### Dexter E Federal #2

Unit Letter G, Sec. 20-T17S-R30E Eddy County, New Mexico

## Mechanically Test Casing

Well Data:

Drilled in 1936

Prod Casing:

7" 24# production casing set at 3000' and cemented

with 100 sx. Calculated TOC is 1500'.

Perfs:

2539-2547', 2611-2614', 2656-2662', 2808-2816' and

2910-2918'. CIBP @ 2870'.

Misc:

Records indicate that there is no tubing in well.

### Procedure:

1. Contact BLM in Carlsbad 48 hours prior to performing test.

- 2. MIRU PU. NU BOP.
- 3. RU WL. Run GR to 2525'.
- 4. RIH with CIBP on WL and set at 2500' (within 50' of top perf).
- 5. Load hole with inhibited fluid. Close rams and pressure test casing to 500 psi for a minimum of 15 minutes. Utilize a chart to verify test and length. Maximum bleedoff is 10% of maximum pressure.
- 6. Release pressure. ND BOP and NU wellhead. Leave well SI in temporary abandoned status.

Doug Keathley


Northern Regional Engineer

# **SOUTHWEST ROYALTIES**

PROJECT Dexter E Fed #2	
Unit 6, Sec 20-TITS-R30E	

OF \
DATE 7/01/93

Present status



8518@ 512' Cut with 60 sx.

TOC = 1600' ( calculated)

Perts 2539-47', 2611-14', 2656-62', 2808-16'.

CIBP@ 2870' with 2 sx cont on top Perfo 2910-2918'.

7" 24 4 casing @ 3000' Cut with 100 sx.

OHTO @ 3275 !

Well 20,1/02 IN 1936'.

# BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

# Temporary Abandonment of Wells on Federal Lands

### Conditions of Approval

According to 43 CFR 3162.3-4-c, "No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544; for wells in Lea County call (505) 393-3612.
- A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
- 3. All downnole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

- 1. Submits a subsequent Sundry Notice requesting TA approval.
- 2. Attaches a clear copy or the original of the pressure test chart,
- And explains why such a well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnessed by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the weil.