

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN 1
(Other instrum.
verse side)DATE*
on re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029342 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal X

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA**Sec. 21, T 17S, R 30E**

12. COUNTY OR PARISH

13. STATE

Eddy**N. Mex.**

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ **DEC 9 1974**

2. NAME OF OPERATOR **Anadarko Production Company**

3. ADDRESS OF OPERATOR **P. O. Box 67, Loco Hills, New Mexico 88255**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface **2310' FSL & 2310' FWL
Section 21, T 17S, R 30E
Eddy County, New Mexico**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3640 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Kill well using 200 bbls. 10% brine water and 25 sz gel/100 bbls. water.
2. Spot 105 sz cement plug from 2920' to 2600', wait 5 hours and tag plug w/wire line. *Wait 4 hrs 5 1/2" Log from approx. 2000-2500'*
3. Spot 35 sz cement plug from 1800' to 1700', wait 5 hours and tag plug w/wire line.
4. Spot 35 sz cement plug 50' below and 50' above base of salt @ 1100', wait 5 hours and tag plug w/wire line.
5. Spot 35 sz cement plug 50' in and 50' out of 8 5/8" casing @ 607', wait 5 hours and tag plug w/wire line.
6. Set 10 sz cement plug and dry hole marker at surface, clean location.
7. No tanks or flow lines on this location.

RECEIVED

DEC - 5 1974

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

**Original Signed By
Jerry E. Buckles**

TITLE

Area Supervisor

DATE

December 3, 1974

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED SUBJECT TO POSSIBLE ADDITIONAL
REQUIREMENT THAT PAD AND/OR ROAD
BE MAPPED AND SEEDED
See Instructions on Reverse SideCONTACT THIS OFFICE REGARDING ABOVE
BEFORE MAKING FINAL CLEANUP.APPROVED
DEC 6 - 1974
H. L. BEEKMAN
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.