

There was an oversight as far as transporter when this 104 was received showing change of operator. The operator notified us last week and this C-104 showing correction in transporter has been filed to correct this oversight. Did not think it necessary to show on change list. All other wells that were changed at this time did show Texas-New Mexico Pipeline, but this one was in a different pool and was Permian, but they listed it wrong.