	Budget	Bures	ea. 1u N	o. 42-R	141
LEASE	DESIGN	ATION	AND	SERIAL	NO.

Other instructions on	Budget	Budget Bureau No. 42-R142		
TENTERIOR (Other lastrocons on	5. LEASE DESIGNA	TION AND SERIAL NO.		
Artesia MM coola	i			

DELAN	LC 053260 060528					
SUNDRY NOTI	6. IF INDIAN, ALLOTTEE OR TRIBE NAME					
1. OIL GAS WELL GAS OTHER	7. UNIT AGREEMENT NAME Grayburg Jackson Unit					
2. NAME OF OPERATOR  General Operating Comp	Tract 2.					
	Suite 1007, Ridglea Bank Bldg., Fort Worth, Texas 76116 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*					
See also space 17 below.) At surface 1980' FSL & 660' FWI Section 26, T175-R30	1	RECEIVED BY	Grayburg Jackson Queen,  11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA			
14. PERMIT NO.	15. ELEVATIONS (Show whet	MAR 04 1986  ther DF, RT, GR, 60. C. D.  3612 DF.	26-T17S-R30E 12. COUNTY OR PARISH 13. STATE Eddy New Mexico			
16. Check Ap		ate Nature of Notice, Report, o	r Other Data			
NOTICE OF INTEN	TION TO:	SUB	SEQUENT REPORT OF:			
FRACTURE TREAT SHOOT OR ACIDIZE	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON® CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report res	ALTERING CASING ABANDONMENT*  sults of multiple completion on Well completion Report and Log form.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- Pull Tubing and Packer
- Ran 7" casing scraper to 3076'
- Ran Bond log. Dresser Atlas Inc. found free pipe at 1900'
- From 1260 1362 7% unbonded pipe signal. Les Clements of O.C.D. Artesia Office suggested not to attempt cement squeeze to bottom of salt.

2/5 to 2/13/86

2/13/86

Cement squeezed four times @ 104' with 125 sacks Class C with 14# flow seal and 10 lbs of salt, 20 lbs of Cal seal, 100 Gallons flow check followed by 25 sacks cement and 100 Gallons flow check then 50 sacks cement.

Test hole at 104' at 300#

Ran 3110' of 2 3/8 tubing with Larkin tension packer circulated 110 barrels packer fluid.

ACCEPTED FOR RECORD

CARLSBAD, NEW .... XICO 18. I hereby certif (This space for Federal or State office APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

> Subject to Like Approval by State

\*See Instructions on Reverse Side