

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRI-STATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
LC 020992 C

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER **Water Injection Well**

2. NAME OF OPERATOR
Anadarko Production Company

3. ADDRESS OF OPERATOR
Box 116 Loco Hills, New Mexico 88255

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
**660' FWL & 1950' FWL
Sec. 26, T 17 S, R 30 E
Eddy County, New Mexico**

7. UNIT AGREEMENT NAME
Grayburg Jackson Unit

8. FARM OR LEASE NAME
Tract No. 9

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Grayburg Jackson

11. SEC., T., R., E., OR BLK. AND SURVEY OR AREA
26-17-30

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3658 LL

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☒

(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Perforated well with 3 1/8" jets from 3150-99, 2/ft. Ran 2" tubing with straddle packers and acidized perfs with 500 gal mud acid. Max press 2100 psi. Final pumping press. 1650 psi @ 1 BPM. ISDP 1500 psi, 15 min 1250. Lowered tubing and packers and straddled existing perfs @ 3218-26 and pumped water into perfs 2 BPM at 1800 Psi., no communication between perfs. Pulled tubing and packers and ran 2" tubing with 1 1/2" tension packer, set at 3175. Connected well and resumed water injection on 12-29-68.

RECEIVED

JAN 22 1969

**O. C. C.
ARTESIA, OFFICE**

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE **15 January 1969**

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

JAN 21 1969

R. L. BEEKMAN

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963—O-685229

GPO 8 37-499

867-851