

Subsequent Report of Sandoil, Page #2
Maddren-Beeson B-1, General American Oil Co. of Tex.

Feb. 5, 1955

RESULTS OF TREATMENT:

1-21-55 Pulled 2-1/2" EUE, re-ran 2" EUE and pumping installation.
1-22-55 Pumped 62 bbls. in 20 hrs.
1-23-55 Pumped 72 bbls.
1-24-55 Pumped 69 bbls.
1-25-55 Pumped 73 bbls.
1-26-55 Pumped 69 bbls.
1-27-55 Pumped 72 bbls.
1-28-55 Pumped 72 bbls. (NET 43 BO).

SUBSEQUENT TESTS:

2-4-55 Pumped 41 BO in 14 hrs.

201.1.1.169

Washington-Deseret B-1, General American 11300 of Des.
Independent Report of General, Page 12

100-443887-1

[illegible]

• 2017 THEORETICAL

100-443887-100