N.M. Oil Cons. Livision

Form 3160-5 811 S. 1st Street (August 1999) 5. Lease Serial No. I C-028992 B SUNDRY NOTICES AND REPORT ON WELLS: NM 88210Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side Gravburg Jackson 1. Type of Well 8. Well Name and No. Oil Well 2. Name of Operator Pendragon Energy Partners, Inc. & 3. Address of Operator 621 17th St., Denver CO 80293 11. County or Parish, State 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Eddy 330' FNL-1650' FEL Sec 27-T17S-R30E 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Water Shut-Off Production (Start/Resume) Acidize Notice of Intent Well Integrity Reclamation Fracture Treat Alter Casino Subsequent Report Other Recomplete **New Construction** Casing Repair Final Abandonment Notice Temporarily Abandon Plug and Abandon Change Plans Water Disposal Plug Back Convert to Injection 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has Present Conditions: 8 5/8" surface casing set @ 491' & cemented w/ 50 sxs. Cement top unknown. determined that the site is ready for final inspection) 7" casing set @ 1805 & cemented w/ 100 sxs. 4 1/2" production casing set @ 3195 cemented w 75 sxs cement. Peforations @ 3106' -17 & 3167-75'. Present status - SI. Proposed P&A Procedure: 1. Set CIBP @ 3080' and spot 35' cement on top of the CIBP. 2. Back off 4 1/2" casing @ a free point and spot 100' cement plug (50' in & 50' out) in the 4 1/2' top 3. Back off the 7" casing @ a free point and spot 100' cement plug (50' in & 50' out) in the 7" top.

- 4. Perforate the 8 5/8" casing @ 50' and circulate the casing & annulus full of cement w/ marker.
- 5. Remove all equipment, clear all debris, back fill any pit and restore surface to original conditions.
- 6. Reseed as required.

	<u> </u>	HENS OF APPROVAL
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) John Luchetta		
Signature Auchetta Da		
THIS SPACE FOR FEDERAL OR S	STATE OFFICE USE	
Approved by	Title P.E.	Date 10/30/00
Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease	Office	

which would entitle the applicant to conduct operations thereon Section 1001 and Title 43 U.S.C. 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.