

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NO.
OF COPIES REC.
(Other instructions on re-
verse side)

BLM Roswell District
Modified Form No.
NMO60-3160-4

4151

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ SWD		3a. Area Code & Phone No. (505) 677-2111	
2. NAME OF OPERATOR Double I, Inc.		8. FARM OR LEASE NAME Wooley Federal	
3. ADDRESS OF OPERATOR P.O. Box 98 Loco Hills, N.M. 88255		9. WELL NO. 1 SWD	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL & 660' FWL		10. FIELD AND POOL, OR WILDCAT Loco Hills Abo	
14. PERMIT NO.		12. COUNTY OR PARISH Eddy	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3637' GL		13. STATE NM	

RECEIVED

DEC 5 '90

O. C. D.

ARTESIA, OFFICE

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Request permission to test for production for 90 days commencing 12/1/90 thru existing Abo perms from 6686' to 6773' which are used for injection. Propose to run and set TAC on 2 3/8" tubing to 6614'. Run pump and rods. Set temporary pumping unit and test to frac tank. Any oil recovered will be transferred to Wooley Fed. #3 Battery. All gas will be flared. If test unsuccessful, will convert back and continue as SWD well.

RECEIVED

NOV 23 8 14 AM '90

18. I hereby certify that the foregoing is true and correct

SIGNED Michael A. Butts

TITLE Gen. Mgr. - I&W, Inc.

DATE 11/12/90

(This space for Federal or State office use)

APPROVED BY Sign. Signed by Adam Salame
CONDITIONS OF APPROVAL, IF ANY:

TITLE PETROLEUM ENGINEER

DATE 12/3/90

Subject to
Like Approval
by State

*See Instructions on Reverse Side