

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

NE OIL CONS. COMMISSION  
Drawer DD  
Artesia, NM 88210  
SUBMIT IN THIS MANNER  
(Other sections on re-verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED APR 22 1993	5. LEASE DESIGNATION AND SERIAL NO. LC-053259A
2. NAME OF OPERATOR Phillips Petroleum Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 4001 Penbrook Street, Odessa, TX 79762		7. UNIT AGREEMENT NAME Grayburg Jackson WFLU
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit D, 990' FSL & 330' FEL		8. FARM OR LEASE NAME Tract MA
14. PERMIT NO. 30-015-04376	15. ELEVATIONS (Show whether OF, WT, GR, etc.) 3628' GL	9. WELL NO. Well #1
		10. FIELD AND POOL, OR WILDCAT Grb.Jacks-SR-Q-Gb-SA
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec.28, 17-S, 30-E
		12. COUNTY OR PARISH Eddy
		13. STATE NM

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRU DDU. NU BOP. Clean out well to 3000'. Set a 5" CIBP at 3000' with tubing. Circulate 5-3/16" casing with 9.5 ppg mud-laden fluid from PBTD 3000'.
2. Spot Plug No. 1 (80 sx. cement) 2200-3000'. Tag.
3. Perforate and squeeze with Plug No. 2 (60 sx. cement) 1250-1350'.
4. Freepoint 5-3/16" casing. Need to pull 596'.
5. Spot Plug No. 3 (175 sx. cement) 3'-646'.
6. RU and 1" outside of 8-5/8" surface pipe with Plug No. 4 (20 sx. cement) 3'-50'.
7. Cut off casing 3' below GL. Install monument marker. Perform reclamation work.

RECEIVED  
MAR 17 10 51 AM '93  
CARTER  
AREA

18. I hereby certify that the foregoing is true and correct

SIGNED L. M. Sanders  
L. M. Sanders

TITLE Supv. Regulatory Affairs

DATE 03-15-93

(This space for Federal or State office use)

APPROVED BY (ORIG. SGD.) DAVID R. GLASS

TITLE PETROLEUM ENGINEER

DATE APR 20 1993

CONDITIONS OF APPROVAL, IF ANY:

SEE ATTACHED

\*See Instructions on Reverse Side