

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN DUPLICATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0139
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

NM OIL
Drawer
Artes

5. LEASE DESIGNATION AND SERIAL NO.

LC-053259A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

CONS COMMISSION
DD

7. UNIT ASSIGNMENT NAME

8. FARM OR LEASE NAME

Grayburg Jackson WFU

9. WELL NO. Tract MA

1

10. FIELD AND POOL, OR WILDCAT

GrbgJacks-SR-Q-Gb-SA

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 28, 17-S, 30-E

12. COUNTY OR PARISH
Eddy

13. STATE
NM

14. PERMIT NO.

30-015-04376

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3628' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 11-13-93 - MIRU Notified BLM of P&A operations prior to start-up. NU BOP. Clean out F/711' T/2110', circ. clean.
- 11-14-93 - Continued to cleanout F/2110' T/3001'. Circ. clean.
- 11-17-93 - Work stuck pipe free - Pull 2 stands. Circ. & wash F/2617' T/2886'. Work stuck pipe. Stuck @2886'. TOOH, left 11 stands 1 single & 27' piece - T.O.F. @2185'.
- 11-18-93 - Engage fish; jar fish free. Rec'd all of fish. Wash & ream 2898'-3024'. Circ. clean.
- 11-23-93 - RU Washover 2970'-3013' (43') Circ. clean.
- 11-24-93 - RU Wash 3168' - 3211'. Circ. hole clean.
- 11-25-93 - Cmt. Mix & pump 80 sks Class C Neat Spot Plug #1 3000'-2200'.
- 11-30-93 - Tag cmt. @2178'. Perf. csg. @1350'. Mix & pump 60 sks Class C Neat Plug #2 1350'-1250'. Contacted Jim Amos w/BLM to obtain approval to not pull 5.1875 casing and to continue plugging by tying cement into surface pipe (perf. csg. 50' below surface shoe & circ. cmt. to surface. Fill casing annulus). Perf. csg. @596'. Mix & pump 230 sks Class C Neat w/circulation to surface.
- 12-01-93 - Perf. csg. @330'. Mix & pump 150 sks. Class C. WOC. Tag cmt. @ 206' Run in hole w/perf gun & perf csg. @200'. Mix & pump 70 sks. Class C Neat w/circulation to surface out 5.1875 x 8.625 annulus & behind 8.625 annulus. Fill 5.1875 annulus w/cement completed plug.

18. I hereby certify that the foregoing is true and correct

SIGNED

L. M. Sanders
L. M. Sanders

TITLE

Supv. Regulatory Affairs

DATE

12-01-93

(This space for Federal or State official use)

(ORIG. SEC.) JOE G. LARA

APPROVED BY

TITLE

Patrolman Engineer

DATE

12/14/93

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side