Novem	unit States vember 1083; merty 9=331; DEPARTMENT OF THE INTERIO	SUBMIT IN TRIPLIC/	SIOExpires August 31, 1985
rorme	DEPARTMENT OF THE INTERIC BUREAU OF LAND MANAGEMENT	Articula, and US210	5. LEASE DESIGNATION AND SERIAL NO.
			LC 028936-g 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	SUNDRY NOTICES AND REPORTS Of the not use this form for proposals to drill or to deepen or plug backuse "APPLICATION FOR PERMIT - " for such project."	ck to a different reservoir	
015	PSA 1441144		UNIT AUREEMENT NAME
WEL ! NAM	E OF OPERATOR	RECEIVED BY	8. FARM OR LEASE NAME
	Yates Petroleum Corporation \checkmark	DEC 12 1985	Brigham
3. ADDI	128S OF OPERATON	DEC 12 1300	9. WELL NO.
4. LOCA	207 South 4th St., Artesia, NM 88210 Articles of Well (Report location clearly and in accordance with any States also space 17 below.)	tati requirements. C. D.	2 10. PIELD AND POOL, OR WILDCAT
See . ≜t ∎	surface	ARTESIA,	Loco HIlls-Q-G-SA
	2310 FSL & 990 FEL, Sec. 31-T17S	-R30E	11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA
			Unit I, Sec. 31-175-30E
14. PERS	in the second (blick whether be, in	T, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	3579' КВ	-	Eddy NM
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		
	NOTICE OF INTENTION TO:		ENT REPORT OF:
TES	T WATER SHUT-OFF PULL OR ALTER CASING	WATER SHCT-OFF	REPAIRING WELL
	CTURE TREAT MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
	OUT OR ACIDIZE ABANDON® X	SHOOTING OR ACIDIZING	ABANDONMENT*
	Det)	(Other)(Nors: Report results	of multiple completion on Well
ropos	RIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent oposed work. If well is directionally drilled, give subsurface location into this work.) See to plug well as follows:	is and measured and true vertical	depths for all markers and zones perti-
sr	not sufficient cement across producing into noe. Tag plug.		
2. Is _2	solate Queen formation from overlying zone 2329'; top of cement is at 1812'.	es with 100' cement p	olug. Top of Queen is at
3. Pe	erforate 50' below base of salt at 1205' ug in casing. Tag plug.	and squeeze with 5	50 sx cement, leaving 100
b1	erforate 50' above top of salt at 385' as ug in casing. Tag plus	f (sa)	
50	et-30 surface plug and install regulation	a abandomment marker.	
NOTE:	1) NOTIFY BLM, CARLSBAD, NM, (887-6544)	24 HOURS PRIOR TO E	BEGINNING WORK.
	2) Mud between plugs to be $10\#/gallon$ m	nud-laden fluid.	
8. 1 bere	by certify that the foregoing is true and correct		
SIGN		luction Supervisor	DATE 11-26-85
(Thing	space for Federal or State office use)		
	OVED BY TITLE		DATE 12:10 65