

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

APR 4 1969

O. C. C.  
ARTESIA, OFFICE

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-2130</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>State BU</b>
9. Well No. <b>6</b>
10. Field and Pool, or Wildcat <b>Loco Hills (G. SA)</b>
12. County <b>Eddy</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator <b>Cities Service Oil Company</b>
3. Address of Operator <b>P. O. Box 69 - Hobbs, New Mexico 88240</b>
4. Location of Well UNIT LETTER <b>P</b> , <b>4950</b> FEET FROM THE <b>North</b> LINE AND <b>990</b> FEET FROM THE <b>East</b> LINE, SECTION <b>32</b> TOWNSHIP <b>17S</b> RANGE <b>30E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>3581 DF</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to plug and abandon the above captioned well in the following manner:

1. Displace 150 sack cement plug through open end tubing from PBTD 3640 to entirely fill 6 1/8" open hole to 7" casing seat at 2994 continuing into 7" casing 100' to 2894'. *See schematic diagram*
2. Cut and pull approximately 2000' of 7" casing.
3. Displace 30 sack cement plug 2050-1950 (1/2 in and 1/2 out of 7" casing stub at 2000')
4. Displace 30 sack cement plug at top of Queen 1350-1250. *Base of Salt*
5. Displace 30 sack cement plug 559-469 (1/2 in and 1/2 out of 8 5/8 casing set at 514')
6. Set 10 sack cement plug in top of 8 5/8 from G.L. to 30' w/a 4" pipe marker extending 4' above the surface to designate a P & A location.
7. Clean all debris and equipment from location.

(See attached schematic diagram)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED ORIGINAL SIGNED  
G. D. ROBERTSON TITLE District Office Manager DATE 4-3-69

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE APR 7 1969  
CONDITIONS OF APPROVAL, IF ANY:  
Load Hole w/mud

# SCHEMATIC DIAGRAM OF STATE BU NO. 6

