Secretarion   Support									
SUNDRY NOTICES AND REPORTS ON WELLS   Subsection of the state of the	٥,	COPILS RECEIVES	1		•			ď	
SUNDRY NOTICES AND REPORTS ON WELLS  SUNDRY NOTICES AND REPORTS ON WELLS  SUNDRY NOTICES AND REPORTS ON WELLS  STATE B-4108  Sta			NEW MEXICO	OU CONS	EDVATION COMMISSION		C-102 and C-1	03	
USANDER SUNDRY NOTICES AND REPORTS ON WELLS  SUNDRY NOTICES AND REPORTS ON WELLS  General American 0f1 Company of Texas  State 8-4108  State 8	<del>-</del>	FE	NEW MEXICO	OIL CONS	ERTATION COmmission		Zitestite jeje	:2	
SUNDRY NOTICES AND REPORTS ON WELLS  SUNDRY NOTICES AND REPORTS ON WELLS  SUNDRY NOTICES AND REPORTS ON WELLS  Consider of the control of the		5.				\ \\ \\ <b>!</b>			
SUNDRY NOTICES AND REPORTS ON WELLS  SUNDRY NOTICES AND REPORTS ON WELLS  Control of the control						أحد			
The politic property of the politic po	OPERA	TOR	_				· .	Ledge .vc.	
State B-4108  7. A principal dispersions General American Oil Company of Texas  7. A principal dispersions F. O. Box 128  8. Loco Hills, New Mexico 88255  7. Locotion of Weil  8. Loco Hills, New Mexico 88255  8. Weil Tex.  9. D. Box 128  8. Loco Hills, New Mexico 88255  8. Weil Tex.  9. D. Box 128  10. Field and Pool, or Wildow 10. Loco Hills  11. Decided Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO:  8. Substitute Insulate Consolium Company of Texas 1980  12. Consulation of Weil  13. Elevation (Show whether DF, NT, GR, etc.)  14. Consulation of Weil  15. Elevation (Show whether DF, NT, GR, etc.)  15. Elevation (Show whether DF, NT, GR, etc.)  16. Consulation of Weil  17. Consulation of Weil  18. Consulation of Weil  19. Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface.  19. Set 10 sack surface plug.  19. Installed permanent dry hole marker.  19. Surface will be cleaned up and pit filled July 8 — 9, 1981.  19. Perforated Weil  19. Perforated Weil  19. Perforated Weil  19. Perforated Weil  19. Perf		SUNDI	RY NOTICES AND REPLECTED FOR PERMIT - " FORM C-1	ORTS ON	WELLS JACK TO A DIFFERENT RESERVOING PROPOSALS.)	A.			
Ceneral American Oil Company of Texas  State B-4108  State B-4108  State B-4108  State B-4108  State B-4108  Loco Hills, New Mexico 88255  Loco Hills, New Mexico 88255  Loco Hills, New Mexico 88255  Loco Hills  West  Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO:  Subsequent Report of Subsequen		1 (1)	OTHER-				7. Unit Agreement	( Ivanie	
P. O. Dox 128 Loco Hills, New Mexico 88255  Locollance (West)  West  C 660  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent TREPORT OF:  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Treport or Other Data Subsequent Treport of Notice, Report or Other Data Subsequent Treport or Other Data Subsequent Treport or Other Data Sub	Name of Operator								
West	3, Agare P	os of Operator  O. Box 128 Loce	o Hills. New Mexic	o 882	55		9. Well No.		
West Unit, Stevenson as North Unit and 1980 rest read Complete Special								="	
The following work was completed June 29 through July 3, 1981:  1. Tagged existing bridge plug @ 2750'.  2. Spotted 14 sacks cement on top of bridge plug and tagged cement plug @ 2700'.  3. Ran stretch survey on 7" casing and found free @ 360'. Too small amount of casing free to warrent pulling.  4. Perforated 4 holes @ 1195' (Base of Salt) and squeezed 55 sacks cement. Tagged this plug @ 422'. Spotted 14 sacks cement on top of this plug to raise it 50'.  5. Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface. Set 10 sack surface plug.  9. Installed permanent dry hole marker.  10. Surface will be cleaned up and pit filled July 8 — 9, 1981.  11. Inberthy centify that the information above is true and complete to the boat of my knowledge and belieft.  Engineer parts.  Engineer parts.		r	660 FEET FROM THE _	North	LINE AND 1980	FEET FROM	Loco Hil	15 ~~~~~~~~~	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  ***COMMINICATION**  ***COMMI	THE		10N TOWNSHI	, <u>17-</u> Sou	1th MANGE 30-East	NMPM.			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:			15. Elevation (Sh	ow whether	DF, RT, GR, etc.)				
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  SUBSEQUENT SUBSECUENT SUBSECUENT OF:  SUBSEQUENT SUBSECUENT SUBSECUENT SUBSECUENT.  SUBSEQUENT SUBSECUENT SUBSECUENT SUBSECUENT SUBSECUENT.  SUBSEQUENT SUBSECUENT SUBSECUENT.  SUBSEQUENT SUBSECUENT SUBSECUENT SUBSECUENT.  SUBSEQUENT SUBSECUENT SUBSECUENT SUBSECUENT.  SUBSEQUENT SUBSECUENT SUBSECUENT SUBSECUENT SUBSECUENT SUBSECUENT SUBSECUENT SUBSECUENT SUBSECUEN							L	VIIIIIII	
The following work was completed June 29 through July 3, 1981:  1. Tagged existing bridge plug @ 2750'.  2. Spotted 14 sacks cement on top of bridge plug and tagged cement plug @ 2700'.  3. Ran stretch survey on 7" casing and found free @ 360'. Too small amount of casing free to warrent pulling.  4. Perforated 4 holes @ 1195' (Base of Salt) and squeezed 55 sacks cement. Tagged this plug @ 1148'.  5. Perforated 4 holes @ 530' (8-5/8" casing shoe) and squeezed 55 sacks cement. Tagged this plug @ 492'. Spotted 14 sacks cement on top of this plug to raise it 50'.  6. Top of Salt was already behind pipe and cement.  7. Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface.  8. Set 10 sack surface plug.  9. Installed permanent dry hole marker.  10. Surface will be cleaned up and pit filled July 8 — 9, 1981.  10. Installed permanent dry hole marker.  10. Surface will be cleaned up and pit filled July 8 — 9, 1981.  10. Installed permanent dry hole marker.  10. Surface will be cleaned up and pit filled July 8 — 9, 1981.	lt.		• • •	ndicate N					
The continue lies of the control of Campleted Crestitions (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see nute lies.  The following work was completed June 29 through July 3, 1981:  1. Tagged existing bridge plug @ 2750'.  2. Spotted 14 sacks cement on top of bridge plug and tagged cement plug @ 2700'.  3. Ran stretch survey on 7" casing and found free @ 360'. Too small amount of casing free to warrent pulling.  4. Perforated 4 holes @ 1195' (Base of Salt) and squeezed 55 sacks cement. Tagged this plug @ 1148'.  5. Perforated 4 holes @ 530' (8-5/8" casing shoe) and squeezed 55 sacks cement. Tagged this plug @ 492'. Spotted 14 sacks cement on top of this plug to raise it 50'.  6. Top of Salt was already behind pipe and cement.  7. Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface.  8. Set 10 sack surface plug.  9. Installed permanent dry hole marker.  10. Surface will be cleaned up and pit filled July 8 — 9, 1981.  18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  19. Title Engineer  10. Surface Will be cleaned up and pit filled July 8 — 9, 1981.	24 b F 08	M REMEDIAL WORK	PLUG AND A	ANDON	REMEDIAL WORK		ALTER	ING CASING	
17. Concention of the proposed of Completed Cycrotions (Clearly state all periode details, and give pertinent dates, including estimated date of startine any proposed work) set Rule 1103.  1. Tagged existing bridge plug @ 2750'.  2. Spotted 14 sacks cement on top of bridge plug and tagged cement plug @ 2700'.  3. Ran stretch survey on 7" casing and found free @ 360'. Too small amount of casing free to warrent pulling.  4. Perforated 4 holes @ 1195' (Base of Salt) and squeezed 55 sacks cement. Tagged this plug @ 1148'.  5. Perforated 4 holes @ 530' (8-5/8" casing shoe) and squeezed 55 sacks cement. Tagged this plug @ 492'. Spotted 14 sacks cement on top of this plug to raise it 50'.  6. Top of Salt was already behind pipe and cement.  7. Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface.  8. Set 10 sack surface plug.  9. Installed permanent dry hole marker.  10. Surface will be cleaned up and pit filled July 8 — 9, 1981.  18. Hereby cently that the information above is true and complete to the best of my knowledge and belief.  19. Till Engineer  10. Surface Will be cleaned up and pit filled July 8 — 9, 1981.		$\equiv$			COMMENCE DRILLING OPHS.		PLUS A	ND ABANDONMENT	
17. Creative Liconoced of Completed Cylerations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE ROLE 1103.  The following work was completed June 29 through July 3, 1981:  1. Tagged existing bridge plug @ 2750'.  2. Spotted 14 sacks cement on top of bridge plug and tagged cement plug @ 2700'.  3. Ran stretch survey on 7" casing and found free @ 360'. Too small amount of casing free to warrent pulling.  4. Perforated 4 holes @ 1195' (Base of Salt) and squeezed 55 sacks cement. Tagged this plug @ 1148'.  5. Perforated 4 holes @ 530' (8-5/8" casing shoe) and squeezed 55 sacks cement. Tagged this plug @ 492'. Spotted 14 sacks cement on top of this plug to raise it 50'.  6. Top of Salt was already behind pipe and cement.  7. Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface.  8. Set 10 sack surface plug.  9. Installed permanent dry hole marker.  10. Surface will be cleaned up and pit filled July 8 — 9, 1981.  18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.  18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.	PULL OF	ALTER CASING	CHANGE PLA	N5					
The following work was completed June 29 through July 3, 1981:  1. Tagged existing bridge plug @ 2750'.  2. Spotted 14 sacks cement on top of bridge plug and tagged cement plug @ 2700'.  3. Ran stretch survey on 7" casing and found free @ 360'. Too small amount of casing free to warrent pulling.  4. Perforated 4 holes @ 1195' (Base of Salt) and squeezed 55 sacks cement. Tagged this plug @ 1148'.  5. Perforated 4 holes @ 530' (8-5/8" casing shoe) and squeezed 55 sacks cement. Tagged this plug @ 492'. Spotted 14 sacks cement on top of this plug to raise it 50'.  6. Top of Salt was already behind pipe and cement.  7. Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface.  8. Set 10 sack surface plug.  9. Installed permanent dry hole marker.  10. Surface will be cleaned up and pit filled July 8 — 9, 1981.  18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  18. Lacrong Engineer  19. July 7, 1981	OTHE	. R			DIALK				
The following work was completed June 29 through July 3, 1981:  1. Tagged existing bridge plug @ 2750'.  2. Spotted 14 sacks cement on top of bridge plug and tagged cement plug @ 2700'.  3. Ran stretch survey on 7" casing and found free @ 360'. Too small amount of casing free to warrent pulling.  4. Perforated 4 holes @ 1195' (Base of Salt) and squeezed 55 sacks cement. Tagged this plug @ 1148'.  5. Perforated 4 holes @ 530' (8-5/8" casing shoe) and squeezed 55 sacks cement. Tagged this plug @ 492'. Spotted 14 sacks cement on top of this plug to raise it 50'.  6. Top of Salt was already behind pipe and cement.  7. Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface.  8. Set 10 sack surface plug.  9. Installed permanent dry hole marker.  10. Surface will be cleaned up and pit filled July 8 — 9, 1981.  18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  18. Lacrong Engineer  19. July 7, 1981	<del></del>		merations (Clearly state all t	ertinent des	ails, and give pertinent dates	, including	estimated date of s	starting any proposed	
<ol> <li>Tagged existing bridge plug @ 2750'.</li> <li>Spotted 14 sacks cement on top of bridge plug and tagged cement plug @ 2700'.</li> <li>Ran stretch survey on 7" casing and found free @ 360'. Too small amount of casing free to warrent pulling.</li> <li>Perforated 4 holes @ 1195' (Base of Salt) and squeezed 55 sacks cement. Tagged this plug @ 1148'.</li> <li>Perforated 4 holes @ 530' (8-5/8" casing shoe) and squeezed 55 sacks cement. Tagged this plug @ 492'. Spotted 14 sacks cement on top of this plug to raise it 50'.</li> <li>Top of Salt was already behind pipe and cement.</li> <li>Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface.</li> <li>Set 10 sack surface plug.</li> <li>Installed permanent dry hole marker.</li> <li>Surface will be cleaned up and pit filled July 8 — 9, 1981.</li> <li>Installed permanent dry hole marker.</li> <li>Surface will be cleaned up and pit filled July 8 — 9, 1981.</li> </ol>	worl	k) SEE RULE 1103.							
<ol> <li>Spotted 14 sacks cement on top of bridge plug and tagged cement plug @ 2700'.</li> <li>Ran stretch survey on 7" casing and found free @ 360'. Too small amount of casing free to warrent pulling.</li> <li>Perforated 4 holes @ 1195' (Base of Salt) and squeezed 55 sacks cement. Tagged this plug @ 1148'.</li> <li>Perforated 4 holes @ 530' (8-5/8" casing shoe) and squeezed 55 sacks cement. Tagged this plug @ 492'. Spotted 14 sacks cement on top of this plug to raise it 50'.</li> <li>Top of Salt was already behind pipe and cement.</li> <li>Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface.</li> <li>Set 10 sack surface plug.</li> <li>Installed permanent dry hole marker.</li> <li>Surface will be cleaned up and pit filled July 8 — 9, 1981.</li> <li>Thereby certify that the information above is true and complete to the best of my knowledge and belief.</li> </ol>	The	e following work w	as completed June	29 thro	ough July 3, 1981:				
<ol> <li>Ran stretch survey on 7" casing and found free @ 360'. Too small amount of casing free to warrent pulling.</li> <li>Perforated 4 holes @ 1195' (Base of Salt) and squeezed 55 sacks cement. Tagged this plug @ 1148'.</li> <li>Perforated 4 holes @ 530' (8-5/8" casing shoe) and squeezed 55 sacks cement. Tagged this plug @ 492'. Spotted 14 sacks cement on top of this plug to raise it 50'.</li> <li>Top of Salt was already behind pipe and cement.</li> <li>Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface.</li> <li>Set 10 sack surface plug.</li> <li>Installed permanent dry hole marker.</li> <li>Surface will be cleaned up and pit filled July 8 — 9, 1981.</li> <li>Thereby certify that the information above is true and complete to the best of my knowledge and belief.</li> </ol>	1.								
<ol> <li>Ran stretch survey on 7" casing and found free @ 360'. Too small amount of casing free to warrent pulling.</li> <li>Perforated 4 holes @ 1195' (Base of Salt) and squeezed 55 sacks cement. Tagged this plug @ 1148'.</li> <li>Perforated 4 holes @ 530' (8-5/8" casing shoe) and squeezed 55 sacks cement. Tagged this plug @ 492'. Spotted 14 sacks cement on top of this plug to raise it 50'.</li> <li>Top of Salt was already behind pipe and cement.</li> <li>Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface.</li> <li>Set 10 sack surface plug.</li> <li>Installed permanent dry hole marker.</li> <li>Surface will be cleaned up and pit filled July 8 — 9, 1981.</li> <li>Thereby certify that the information above is true and complete to the best of my knowledge and belief.</li> </ol>	2.								
9 1148'.  5. Perforated 4 holes @ 530' (8-5/8" casing shoe) and squeezed 55 sacks cement. Tagged this plug @ 492'. Spotted 14 sacks cement on top of this plug to raise it 50'.  6. Top of Salt was already behind pipe and cement.  7. Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface.  8. Set 10 sack surface plug.  9. Installed permanent dry hole marker.  10. Surface will be cleaned up and pit filled July 8 — 9, 1981.  18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.  Signify Title Engineer  PATE July 7, 1981	3.	Ran stretch survey on 7" casing and found free @ 360'. Too small amount of casing free to warrent pulling.							
plug @ 492'. Spotted 14 sacks cement on top of this plug to raise it 50'.  6. Top of Salt was already behind pipe and cement.  7. Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface.  8. Set 10 sack surface plug.  9. Installed permanent dry hole marker.  10. Surface will be cleaned up and pit filled July 8 — 9, 1981.  18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNED	4.	Perforated 4 holes @ 1195' (Base of Salt) and squeezed 55 sacks cement. Tagged this plug @ 1148'.							
7. Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface.  8. Set 10 sack surface plug.  9. Installed permanent dry hole marker.  10. Surface will be cleaned up and pit filled July 8 — 9, 1981.  18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  Signed Title Engineer Date July 7, 1981	5.	Perforated 4 hole plug @ 492'.	erforated 4 holes @ 530' (8-5/8" casing shoe) and squeezed 55 sacks cement. Tagged this plug @ 492'. Spotted 14 sacks cement on top of this plug to raise it 50'.						
7. Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface.  8. Set 10 sack surface plug.  9. Installed permanent dry hole marker.  10. Surface will be cleaned up and pit filled July 8 — 9, 1981.  18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  Signed Title Engineer Date July 7, 1981	6.	, ·							
8. Set 10 sack surface plug.  9. Installed permanent dry hole marker.  10. Surface will be cleaned up and pit filled July 8 — 9, 1981.  18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNED		7. Perforated 4 holes @ 300' (water zone) and squeezed 55 sacks. No circulation to surface							
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNED	8.	8. Set 10 sack surface plug.							
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNED		Installed permanent dry hole marker.							
SIGNED TITLE Engineer DATE July 7, 1981								1	
	18. I he	reby certify that the information	on above is true and complete	to the best	of my knowledge and belief.				
DATE	SIGNED	m. 8. San		TITLE	Engineer		DATE July	7, 1981	
DATE	=====		-	<del></del>					
				TITLE			DATE		

CONDITIONS OF APPROVAL, IF ANY: