

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-04439
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-4108
7. Lease Name or Unit Agreement Name Tallmadge
8. Well No. 1
9. Pool name or Wildcat Loco Hills Queen G-SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED
2. Name of Operator YATES PETROLEUM CORPORATION	JUN 29 '94
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	C. C. D. ARTESIA OFFICE
4. Well Location Unit Letter N : 990 Feet From The South Line and 1650 Feet From The West Line Section 32 Township 17S Range 30E NMPM Eddy County	10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: Temporary Abandon <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to temporary abandon as follows:

1. POOH with tubing and packer.
2. RIH w/bit and scraper on tubing and clean out to 2700'. POOH.
3. GIH w/7" CIBP and set at 2655'. Dump 35' of cement on top of CIBP.
4. Pressure test casing to 500 psi. NOTE: Have OCD officials witness the test.
5. If casing tests okay, install pressure guage and move out pulling unit.

If casing does not test, will plug and abandon well as follows:

1. GIH w/perforating gun and perforate 4 holes at 2339'. POOH. GIH w/cement retainer on 2-3/8" tubing and set cement retainer at 2259'. Squeeze Queen with 50 sacks Class "C" 2% CaCl2. Dump 35' of cement on top of cement retainer. POOH.

CONTINUED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 6-28-94
TYPE OR PRINT NAME Rusty Klein 505-748-1471
TELEPHONE NO.

(This space for State Use)

SUPERVISOR, DISTRICT II

JUL 11 1994

TITLE _____ DATE _____

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-015-04439

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-4108

7. Lease Name or Unit Agreement Name

Tallmadge

8. Well No.

1

9. Pool name or Wildcat

Loco Hills Queen G-SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South Fourth Street - Artesia, NM 88210 ARTESIA, OFFICE

4. Well Location

Unit Letter N : 990 Feet From The South Line and 1650 Feet From The West Line

Section

32

Township

17S

Range

30E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: Temporary Abandon ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CONTINUED:

2. GIH w/perforating gun and perforate 4 holes at 1175'. POOH. GIH w/cement retainer on 2-3/8" tubing and set cement retainer at 1125'. Squeeze Base of Salt with 50 sacks Class "C" 2% CaCl₂. Dump 35' of cement on top of cement retainer. POOH.
3. Perforate 4 holes at ~~460~~ 480. GIH w/cement retainer on 2-3/8" tubing and set cement retainer at 410'. Squeeze Top of Salt with 50 sacks Class "C" 2% CaCl₂. Dump 35' of cement on top of cement retainer. POOH.
4. RIH w/perforating gun and perforate 4 holes at 250'. Pump 50 sacks Class "C" out of holes and leave 100' of cement in casing. WOC.
5. RIH and tag plug at 150' or higher.
6. 15 sack cement plug at surface (at least 50').
7. Install regulation abandonment marker.

NOTE: Heavy mud will be placed between all plugs.
NOTIFY OCD (748-1283) AND BLM (887-6544) 24 HOURS PRIOR TO COMMENCING OPERATIONS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Rusty Klein

TITLE Production Clerk

DATE 6-28-94

TYPE OR PRINT NAME

Rusty Klein

505-748-1471
TELEPHONE NO.

(This space for State Use)

DATE