

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPL  
(Other instructions on  
reverse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 028936 D

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

JUN 29 1976

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Water Injection

2. NAME OF OPERATOR

Anadarko Production Company

O. C. C.  
ARTESIA, OFFICE

3. ADDRESS OF OPERATOR

P. O. Box 67, Loco Hills, New Mexico 88255

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)  
At surface1650' FSL & 1650' FSL Sec. 31, T17S, R30E  
Eddy County, New Mexico

7. UNIT AGREEMENT NAME

Anadarko Premier L & M  
Waterflood Project

8. FARM OR LEASE NAME

Federal M

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Loco Hills

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

31 - 17S - 30E

12. COUNTY OR PARISH 13. STATE

Eddy New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Convert to Producing well X

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Rig up Pulling Unit, pull tubing and packer.
2. Set 4 1/2" cement retainer at 2820'.
3. Cement squeeze Loco Hills perforations 2846' - 56'.
4. Run 4 1/2" packer and locate old hole in casing at approximately 700'.
5. Set squeeze packer 200' above casing hole and cement squeeze.
6. Drill out cement to TD of 3109'.
7. Perforate Premier Zone 3084' - 92' @ 2 SPF.
8. Fracture treat Premier Zone w/30,000 gals gelled water & 30,000# sand.
9. Set pumping unit, run rods and tubing.
10. Put well on production.

11. Note: All production will be from the Grayburg Formation.

Note: Anadarko Premier L & M Waterflood Project is a new State  
N. M. O. C. C. designation as specified in Order No. R-5224 dated  
June 1, 1976. I will file subsequent application with U. S. G. S  
later this month.

18. I hereby certify that the foregoing is true and correct

SIGNED

Original Signed by  
Jerry E. Buckles

TITLE

Area Supervisor

DATE

June 22, 1976

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: