C:5F

	-		- 4	
Form 9-331	Ŀ TE	ED STATES	SUBMIT IN TRA	
(May 1963)	DEPARTMENT OF THE INTERIOR (Other instructions on verse side)			5. LEASE DESIGNATION AND SERIAL NO.
GEOLOGICAL SURVEY			LC 031844	
SUNDRY NOTICES AND REPORTS ON WELLS				6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for sup persons. F V E D				1 5 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
(DO NOT dae this	Use "APPLICATION FO	OR PERMIT—" for supply	PPOEFIVED	
1.				7. UNIT AGREEMENT NAME
WELL X GAS WELL	OTHER P&A	<del></del>	<b>.444</b> 1 3 1979	8. FARM OR LEASE NAME
2. NAME OF OPERATOR				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Atlantic Ri	chfield Company		nr.	9, WELL NO.
••	P. O. Box 1710, Hobbs, New Mexico 88240 ARTESIA, OFFICE			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*				10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface				Grayburg Jackson
330' FNL & 330' FEL (Unit letter A)				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
				Sec 1, T17S, R31E
		(0)		12. COUNTY OR PARISH 13. STATE
14. PERMIT NO.	15. EL	EVATIONS (Show whether I		
	4060' GR			Eddy N.M.
16.	Check Appropria	ite Box To Indicate	Nature of Notice, Report, or (	Other Data
	NOTICE OF INTENTION TO:	:	BUBSEQ	UENT REPORT OF:
TEST WATER SHUT-	PULL OR	ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	· · · ·   <del> - · ·  </del>	E COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON	•	SHOOTING OR ACIDIZING	ABANDONMENT* X
REPAIR WELL	CHANGE I	PLANS	(Other)	s of multiple completion on Well
(Other)			Completion or Recomp	pletion Report and Log form.)
proposed work. I nent to this work.)	f well is directionally dri	illed, give subsurtace loc	cations and measured and true vertice	s, including estimated date of starting any cal depths for all markers and zones perti
Proposed pl	ans to P&A have	been complete	ed and was done in the	following manner.
				llass II omt gamaga 51"
2/19/74 - Loaded hole w/fresh water gel mud. Spotted 35 sx Cl csg shoe @ 3755'. TOC @ 3450'. Spotted 20 sk cmt plug 2965-3				3140' Cut 5½" ces @
free point 2095' & pulled 67 jts of $5\frac{1}{2}$ " 14# J-55 csg. Spotted 35 sx cmt plug @				
$5\frac{1}{2}$ " csg stub 2000-2150'. Spotted 35 sk cmt plug across 8-5/8"				" csg shoe 750-850".
Cut 8-5/8"	csg @ 450', una	able to circula	ate free. Backed off	top 2 jts of 8-5/8"
csg. Spott	ed cmt 30 sk cm	nt plug 70' to	surface. Erected dry	hole marker. Well
P&A 2/22/74. Clean & level location. Your office will be not				tified when location
is ready for inspection.				
				[#취영관절 - 출 경하는]
			RECEIVE	
			11202.12	CANCEL AND SECULATION OF THE SECURATION OF THE S
			MAR - 1 1974	10 1 0 1 0 1 0 1 0 1 1 0 1 1 1 1 1 1 1
				開門前は島 教育 注う担口
			LL S. GEOLOGICAL SU	
			Artesia, New Mex	
18. I hereby certify that	the foregoing is true as	nd correct		
SIGNED	Gamas	TITLE _	Dist. Drlg. Supv.	DATE 2/27/74
	1 3 9 1 2			
(This space for Fed	leral or State office use	1 Lan	CTINE DIRTHIET SMEINEE	Real of the first state
APPROVED BY	DONORAL IN ANTE	XCOM TITLE	• • • • • • • • • • • • • • • • • • •	DATE JUL 11 1979
CONDITIONS OF	APPROVAL, IF ANY:			
•				# 6.1
		<b>*C</b> 1	. D Ct.l.	ಕಕ್ಕಾಗಿ ೫ 2.86