

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐

2. NAME OF OPERATOR ARCO Oil and Gas Company

Division of Atlantic Richfield Company

3. ADDRESS OF OPERATOR

P. O. Box 1710, Hobbs, New Mexico 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 440' FSL & 440' FWL

AT TOP PROD. INTERVAL: as above

AT TOTAL DEPTH: as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☒  
(other) ☐

SUBSEQUENT REPORT OF

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

RECEIVED

JUN 1 1983

OIL & GAS

ROSWELL, NEW MEXICO

5. LEASE

LC-029435(a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

RECEIVED BY

8. FARM OR LEASE NAME

J. L. Keel A

OCT 11 1983

9. WELL NO.

2

O. C. D.

ARTESIA, OFFICE

10. FIELD OR WILDCAT NAME

Grayburg Jackson (QGSA)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

7-17S-31E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3745' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Propose to plug and abandon. Well casing beyond repair.

1. RIH w/pkr, set pkr @ 1540', establish pump in rate thru holes in 6-5/8" csg. POH w/pkr. Set cmt retr @ 1540' & cmt squeeze w/amt cmt determined by pump in rate, spot 35' cmt on top of retr.
2. Perf 4 holes @ 1340'. Set cmt retr @ 1100' & cmt squeeze thru perfs w/C1 H Neat cement. Spot 35' cmt on top of retr.
3. Perf 4 holes @ 500'. Pump 250 sx C1 H Neat cmt from surf, fill csg to surf w/cmt. Cut off csg below GL, weld on regulation dry hole marker. Clean & level location for abandonment.

Above P&A procedures approved verbally between ARCO representative Liz Bush and BLM Peter Chester & Mike Stubblefield on 5/27/83.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Peter W. Chester TITLE Drlg. Engr. DATE 5/31/83

APPROVED

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd) PETER W. CHESTER TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

OCT 6 1983