

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TR (Other instructions on reverse side)
CATE*
Copy to J.

Form approved.
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

Las Cruces 029435 b

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Sinclair Oil & Gas Company ✓		8. FARM OR LEASE NAME J. L. Keel "B"	
3. ADDRESS OF OPERATOR P. O. Box 1920, Hobbs, New Mexico		9. WELL NO. 6	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' from the North line and 1980' from the West line		10. FIELD AND POOL, OR WILDCAT Grayburg-Jackson	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 8-T178-R31E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3753' GR		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☒	ABANDONMENT*	☐
(Other) Deepen	☒		☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4-6-65 Move in cable tools and clean-out @ 3000' in shot hole from 2990'.
4-7-65 to
4-24-65 Drill Gray Line.
4-29-65 Run 2-3/8" tubing and Packer to 3413' w/ 5/8" pipe @ 3420' and acidize Grayburg open hole 3413' - 3680' w/ 2,000 gals. B.D.A. Max. Press. 2800#, Min. 1700# @ 3.2 BPM Inst. SIP 1900#, 10 min. SIP 1400#.
4-30-65 Run 2-7/8" OD tubing to 2855'. Run rods and 2" bore pump.
5-3-65 On potential test 24 hrs. ending 6:00 AM 5/3/65 pumped Grayburg open hole 2856' to 3680' 95 BHO Gty 34.6, no water GOR 370:1. Recompleted after deepening 3400' to 3680'.

RECEIVED

MAY 11 1965

U. S. G. E.
ARTESIA, NEW MEXICO

MAY 6 1965
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Superintendent DATE 5-5-65

(This space for Federal or State office use)

APPROVED
CONDITIONS OF APPROVAL, IF ANY:
MAY 10 1965
RUDOLPH C. BAER, JR.
ACTING DISTRICT ENGINEER

TITLE _____ DATE _____

*See Instructions on Reverse Side

Originals: 100-1000, 100-1000, 100-1000, 100-1000

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.