

UNITED STATES
DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Copy to SF
Form approved.
Budget Bureau No. 42-R1424.

GEOLOGICAL SURVEY N. M. O. C. C. COPY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME Skelly Unit	
2. NAME OF OPERATOR Getty Oil Company		8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR P. O. Box 730; Hobbs, New Mexico 88240		9. WELL NO. 33	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit M, 660 FSL and 660 FWL		10. FIELD AND POOL, OR WILDCAT Grayburg-Jackson	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3323' DF	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 14-17S-31E		12. COUNTY OR PARISH Eddy	
13. STATE New Mexico			

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		

(Other) xxx - Bring cement top up

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pull rods and tubing.
2. Run cement bond logs.
3. Perforate and bring cement top above 7-Rivers.
4. Run temperature survey.
5. Rerun tubing and rods.
6. Place well back on production.

RECEIVED

AUG 10 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Alfred G. Carter TITLE Area Superintendent DATE August 9, 1977

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

APPROVED

AUG 16 1977

R. L. BERNARD
DISTRICT ENGINEER