

8-31-79 1:30 p.m. had a call from Phil Call with ARCO

Turner B #3-D, 20-17-31 has been shut-in but they now have it repaired and have resumed injection. Well had hole in tubing.

They did not use plastic tbg. But did use good tbg.

*JW*

---