Form 3160-5 (JUNE 1990)

N.M. Oil Cons.

P.O. Box 1980

FORM APPROVED

c/sF

. . red states

DEPARTMENT OF THE INTERIOR Hobbs. NM 88241

dget Bureau No. 100)4-0135
---------------------	---------

BUREAU OF LAND MANAGEMENT		Expires March 31, 1993	
SUNDRY NOTICES AND REPORTS ON WELLS		5. Lease Designation and Serial No.	
Do not use this form for proposals to still or to deepen or reentry to a different reservoir Use "APPLICATION FOR PERMIT -" for such proposals		6. If Indian, Allotte or Tribe Name	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation	
1 Type of Well	Oil Well Gas Well	Other X Water Injection	Skelly Unit
2. Name of Operator		8. Well Name and Nc.	
The Wiser Oil Company			
3 Address and Telephone No.		9. Well API No.	
2145 P		30-015-05331	
8115 Preston Road, Suite 400, Dallas, 1X /5225 (214)265-0080		10. Field and Pool, or Exploratory Area Grayburg Jackson 7-Rivers-QN-GB-SA	
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State	
Unit M, 530' FSL & 330' FWL, Sec 21, T17S, R31E		ARTES A Edd New Mexico	
12.		te Nature of Notice, Report, or Other Da	TYPE OF ACTION
ТҮРЕ	OF SUBMISSION		THEOFACTION
[Notice of Intent	Abandonment	Change of Plans
L		Recompletion	New Construction
	Subsequent Report	Plugging Back	Non-Routine Fracturing
Casing Repair		Water Shut-Off	
	Final Abandonment Notice	Altering Casing	X Conversion to Injection
<u> </u>	· · · · · · · · · · · · · · · · · · ·	Other	Dispose Water
			(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form)
13 Describe Proposed or Co subsurface locations and	ompleted Operations (Clearly state all pertiner measured and true vertical depths for all mar	t details, and give pertinent dates, including estin kers and zones pertinent to this zone).*	imated date of starting any proposed work If well is directionally drilled, give
06/30/97	MIRU DA&S WS. RIH w/7" pkr & set @ 3007'. Load csg & test to 500#. Held ok. Rlsd pkr. POH.		
07/02/97	RIH w/shoe & 3 jts, 3-13/16" wash pipe. Tagged liner @ 3151'. Went into liner to 3233'. Wash down to 3345'. Blew hole in csg 1 ft. Below WH. RIH w/R-4 pkr. & set @ 10'. Stripped off BOP's. Repaired csg. POH w/pkr. NU BOP. RIH w/shoe, wash pipe & 2-3/8" tbg. to 3000'.		
07/03/97	RIH & tagged @ 3345'. Cut over fish to 3275'. Quit making hole. POH & LD 56' 2-3/8" tbg. RIH w/3-7/3" x 3-13/16" shoe & 2 jts 3-13/16" wash pipe on 2-3/8" tbg. Tagged @ 3274'. Drld scale to 3293'. Shoe plugged & quit making hole. POH & LD pieces of tbg.		
07/07/97	RIH w/3-7/8" x 3-13/16" shoe, 2 jts. 3-13/16" wash pipe & 2-3/8" tbg. Tagged @ 3293'. Washed & drld scale to 3420'. POH & LD shoe, 1 jt. wash pipe & 15' of fish. RIH w/3-7/8" x 3-13/16" shoe, 1 jt. wash pipe & 2-3/8" tbg. Tagged @ 3420'. Washed & drld scale to 3720'. POH & LD shoe, wash pipe & rest of fish. Dumped 50 sks. sand		
07/08/97	POH & LD shoe, wash pipe & rest of fish. Dumped 50 sks. sand RIH w/notched collar, SN & 2-3/8" tbg. Tagged sand @ 3410'. Washed sand to 3450'. LD work string. Wtd on IPC tbg. RIH w/7" Baker J-Lok pkr. w/1-½" profile nip & 94 jts. tbg. Circ. pkr. fl & set pkr. @ 2961'. Tstd csg. to 500#. Left 500# on csg.		
07/09/97	RU HES & acidized pper Vacuum/Grayburg perfs w/7500 gals 15% Fer-check acid + 1,000# rock salt in 3 stages. ATP 2100# @ 4.4 bpm. MTP 2406# @ 4.7 bpm. ISIP 1630#. 5 min 1598#, 10 min 1585#, 15 min 1575#. NU WH.		
07/16/97	Initial injection rate 300 BWPD @ 600#.		
14 I hereby certify that the	foregoing is true and correct		
Signed.	the Esil	Title Production Administrator	Date 01/16/98
		1	i e e e e e e e e e e e e e e e e e e e

(THIS SPACE FOR FEDERAL OR STATE OFFICE USE) Approved By

Title

department or agency of the United States any false, ficticious or fraudulent statments or representations Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any

as to any matter within its jurisdiction

Conditions of approval, if any

EDDY CO. Nim THE - THIS RAIL TIONS A SECONDARY M = 16 205 /m SOLLO 1.