

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

ARTESIA, N.M. 87003-1000

SUBMIT IN TRIPLICATE *
(Other Instructions on
reverse side.)Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT - " for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> WIW		5. LEASE DESIGNATION AND SERIAL NO. LC-029418-B NM 98120
2. NAME OF OPERATOR The Wiser Oil Company /		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 2568 Hobbs, New Mexico 88241		7. UNIT AGREEMENT NAME Skelly Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 660' FEL Unit I		8. WELL NAME AND NO. 70
14. PERMIT NO		9. API WELL NO. 30-015-05365
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3881' DF		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson 7-Rivers-QN-GB-SA
16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 23-T17S-R31E
12. COUNTY OR PARISH Eddy County		13. STATE NM

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT * ☒

(Other) TA to water injection

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

09/13/99 MIRU Tatum WS. Cut WH. NU BOP's. RIH w/3-7/8" bit, 1 jt. 2-3/8" tbg., 4-3/4" string mill & 100 jts. 2-3/8" tbg. Washed sand f/3122' to 3193'. Tagged liner top w/mill @ 3162'. LD tbg., mill & bit.

09/14/99 RIH w/csg. alignment tool & 4-1/2" csg. Csg. shoe @ 3161'. End of tool 3171'. Float collar @ 3104.32'. Flange up WH. Circulated 45 min. RD reverse unit.

09/15/99 Cut off csg. Weld on bell nipple. RU Dowell & cemented 4-1/2" csg. w/300 sks. 65-35 POZ cmt. w/6% gel, 9# salt/sk. & 50 sks. class "C" w/2% CaCl2. Plug down @ 11:47 a.m. Circulated 25 bbls. out of 7"- 4-1/2" annulus. Float held. RDMO.

06/01/00 MIRU Tyler WS. ND WH. RIH w/3-7/8" bit, bit sub, DC's & 2-3/8" tbg. to 3106'. Tagged wiper plug. Drilled out to 3151'. POH to 3100'.

06/02/00 RIH & tagged @ 3151'. Drilled to 3161'. Tagged alignment tool. Drilled thru tool to 3170'. POH to 3100'.

06/05/00 Tagged @ 3170'. Drilled cmt. to 3180'. Tested csg. to 500#. Held ok. RIH to 3200'. Tagged sand & washed to 3250'. Drilled CIBP @ 3250'. Fell to 3344'. Drilled sulfate scale to 3560'. Drilled carbonate scale & iron to T.D. 3881'. Circulated hole clean.

06/06/00 LD tbg. & collars. RU WL. Ran DSN f/3876'-1875'. RD WL. ND BOP's. RDMO.

18. I hereby certify that the foregoing is true and correct.

SIGNED Mary Jo Turner TITLE Production Tech II DATE April 2, 2001

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instruction On Reverse Side

