

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
NEW OIL CONS. COMMISSION
SUBMIT IN TRIPlicate
(Other instructions on reverse side)
Artesia, NM 88210

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back or to alter a reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Inj. well

2. NAME OF OPERATOR

Getty Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 730, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit Ltr L, 2130 FSL & 660 FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3866' DF

5. LEASE DESIGNATION AND SERIAL NO.

LC-029418 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Skelly Unit

9. WELL NO.

73

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson Fren 7-

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

River

23, 17S, 31E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

XX

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Rig up pulling unit.
2. Install B.O.P.
3. Pull tubing (both strings)
4. Run a bit and scraper to T.D.
5. Set a BP @ $\pm 2200'$.
6. Perf two holes @ $\pm 729'$.
7. Cement w/360 sx of cement.
8. Drill out and move plug to $\pm 2490'$.
9. Acidize 7-Rivers zone
10. Flow well back.
11. Return to injection.

18. I hereby certify that the foregoing is true and correct

SIGNED

Dale R. Crockett

TITLE Area Superintendent

DATE 6/25/84

(This space for Federal or State office use)

APPROVED BY

TITLE P.E.

DATE 7/9/84

CONDITIONS OF APPROVAL, IF ANY:

0+6-BLM-Carlsbad 1-File
1-Engr. PWS 1-Foreman EF
1-Mr. J.A.-Midland

Subject to
Like Approval
by State
See Instructions on Reverse Side