

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JUN

ARTESIA, NEW MEX.

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.
E 4201

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Hugh L. Johnson Sr.	8. Farm or Lease Name Continental St.
3. Address of Operator Unknown	9. Well No. 5
4. Location of Well UNIT LETTER C 330 FEET FROM THE N LINE AND 1902 FEET FROM THE W LINE, SECTION 30 TOWNSHIP 17S RANGE 29E NMPM.	10. Field and Pool, or Wildcat Cibola
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

REMEDIAL WORK	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>
CASING TEST AND CEMENT JOBS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

ALTERING CASING	<input type="checkbox"/>
PLUG AND ABANDONMENT	<input checked="" type="checkbox"/>
OTHER	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Order R 5806

Well plugged and abandoned as follows 4-15-19-79

ID 951 '898"-342-50

- (1) Loaded hole w/mud laden fluid
- (2) Set 35 sx. plug @ 948'
- (3) Set 35 sx. plug @ 648' & Tag @ 571'
- (4) Set 35 sx. plug @ 400' & Tag @ 279'
- (5) Set 15 sx. plug @ surface & 7 sx. in cellar.
- (6) Erect marker.
- (7) Clean Location

used reverse limit to 20
from 386 to 947

Lost Circ. @ 388

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Benny Carter

Hobbs Pipe & Supply
TITLE Manager

DATE 6/8/79

APPROVED BY W. A. Gressett

TITLE SUPERVISOR, DISTRICT II

DATE JUN 13 1979

CONDITIONS OF APPROVAL, IF ANY: