

Operator _____
Well _____
Unit _____ Section _____ Township _____ Range _____
API # 30-0 _____ -- _____

TOPS

T. Salt 6.75
B. Salt 1700
Yates 1362
Glorieta _____
Delaware _____
Bone Sp. _____
Abo _____
Wolfcamp _____
Morrow _____
Devonian _____
Fusselman _____
Other _____

- Contact OCD 24 hrs. prior to any work done.
- Salt gel mud consisting of 10# brine with 25# of gel per barrel must be placed between each plug
- Install dry hole marker as per rule 202.B.2
- Plugs are to be set from point indicated up. Plugs must not be less than 100' or 25 Sacks of cement, whichever is greater, unless specifically indicated.
- Shoe and stub plugs will be 50' above and below shoe or stub and tagged.
- Surface plug will be from 0' - 60'
- Where plugs are required cement must be placed inside and outside of all casing string(s), in the correct footage or sacks required, if no cement exists.
- Plugs to be tagged will be indicated.

626'
85/8
11.14e
3535X
Cmc

PR-TO Shows 1735' 10-25-01

3313-3618 + Prob
3660' ← → CTSP-1960
3842-3903 + Prob

7444e
10-25-01

3925'

Band log Shows TOC @ Surface 10-25-01