

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

AUG 9 1967

O. C. C.

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-1266
7. Unit Agreement Name
8. Farm or Lease Name G-J West Coop Unit
9. Well No. 23
10. Field and Pool, or Wildcat Grayburg-Jackson
12. County Eddy

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Penneco Oil Company
3. Address of Operator Box 1031, Midland, Texas 79701
4. Location of Well UNIT LETTER 0, 1980 FEET FROM THE east LINE AND 660 FEET FROM THE south LINE, SECTION 21 TOWNSHIP 17-S RANGE 29-S NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3554 GR

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1708.

#### PROCEDURE:

1. Pulled and laid down rods and tbq. Moved off pulling unit.
2. Perforated with one 3/8" jet, 2217, 2229, 2244, 2249, 2253, 2271, 2285, 2291, 2300, 2312, 2323, 2340, 2346, 2355, 2363, 2369, 2473, 2485, 2496, & 2504. Set retrievable bridge plug on wire line at 2530. Dumped 500 gal. mud acid down csg.
3. Frac down csg. with 50,000 gallons gelled water and 75,000# 20-40 sand. Overflushed with 10 BW.
4. Shut-in overnight.
5. Bled off pressure, ran tbq. w/retrieving head and recovered bridge plug.
6. Ran tbq. and rods and put on pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>District Prod. Engineer</u>	DATE <u>8-8-67</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL &amp; GAS COMMISSIONER</u>	DATE <u>8-8-67</u>

CONDITIONS OF APPROVAL, IF ANY:

