

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLES  
(Other Instructions  
reverse side)

E-  
F-

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-074937

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Parke "F"

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Grayburg-Jackson

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 10, T-17S, R-30E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug but use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

FEB 11 1980

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

General American Oil Company of Texas

3. ADDRESS OF OPERATOR

P. O. Box 128 Loco Hills, New Mexico 88255

4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations. See also space 17 below.)

At surface

1980' FSL and 660' FEL

FEB 12 1980

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, BK, etc.)

3720 RT ARTESIA, OFFICE

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☒

PULL OR ALTER CASING

☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other) Re-cement

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐

REPAIRING WELL

☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

We Propose To:

1. Dig small workover pit.
2. Pull Rods and Tubing.
3. Set retrievable bridge plug below area to perforate (approximately 2,000').
4. Re-cement across Seven Rivers zone.
5. Drill out cement.
6. Log and perforate Seven Rivers zone.
7. Sand frac Seven Rivers zone.
8. Retrieve bridge plug and return well to production.

18. I hereby certify that the foregoing is true and correct

SIGNED Leland B. Harkness TITLE Assistant Field Superintendent DATE February 8, 1980

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE [Signature] DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY: