orm 3160-5 Jui

Approved by Signed by Shannon J. Share Conditions of approval, If any:

UNITED STATES

 NM	OIL	CONSRIGONALS ELON Diget Bureau No. 1004-0135 Expires: March H. 1993	
Dr	awer	Diget Bureau No. 1004-0135	
Ar	Lagi	Expires: March 31, 1993	

IL	cohs _r compassion	161
	Dig et Bureau No. 1004-0135	c\51
بنع	Expires: March 31, 1993 ase Designation and Serial No.	
. Lei	ase Designation and Serial No.	

12/19/94

Date

June 1990)		AND MANAGEMENT	Prawer Biget Bureau No. 1004-0135 (\) Expires: March 11, 1993 5. Lease Designation and Serial No.					
Do not use this	SUNDRY NOTICES form for proposals to dri Use "APPLICATION FOR	LC028784B 6. If Indian, Allottee or Tribe Name						
	SUBMIT	7. If Unit or CA, Agreement Designation						
I. Type of Well Oil Gas Well Well Name of Operator	1 Other	Burch Keely Unit 8. Well Name and No.						
•	rgy Corporation	Burch Keely Unit #6						
P.O. Drawer		30-015-20622 10. Field and Pool, or Exploratory Area						
	age, Sec., T., R., M., or Survey Des	Grbg. Jakeson SRQ Grbg. SA						
660 FNL 6	17 FWL, Sec. 18 T-17	Eddy Co., N.M.						
CHECK	APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA					
TYPE OF	TYPE OF SUBMISSION TYPE OF ACTION							
Notice of	of Intent	Abandonment	Change of Plans					
Subsequ	sent Report	Recompletion Plugging Back	New Construction Non-Routine Fracturing					
	bandonment Notice	Casing Repair Altering Casing	Water Shut-Off Conversion to Injection					
		Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)					
. Describe Proposed or Co give subsurface loca	ompleted Operations (Clearly state all parties and measured and true vertical	ertinent details, and give pertinent dates, including estimated date of starting depths for all markers and zones pertinent to this work.)*	any proposed work. If well is directionally drilled.					
 Tubing Stuck unable to pull any tubing out of hole. Pumped 80 sacks of cement down tubing to bottom attempt to leave cement top at 2400' W.O.C. tag cement top at 2438' Perferate 2 3/8 tubing at 4 1/2 casing at base of salt 875' squeeze perferations down tubing cement between 2 3/8 tubing & 4 1/2 casing and 4 1/2 casing and open hole W.O.C. tag cement top at 690' Perferate 4 1/2 casing at 550' 8 5/8 casing shoe and squeeze W/50 sacks cement W.O.C. tag cement top at 350' Perferate 4 1/2 casing at 8 5/8 at 50' circulate cement to surface W/50 sacks of cement and set P.A. marker 								
	mpleted 12/19/94							
	Seceined	Post ID 3-10-9	-2					
	FEB 27 1995	3-10-9 84 A						
©	IL CON. DIV. Dist. 2	Approved as to plugging of the well bore. Unability under bond is retained until surface restoration is completed.						
I hereby certify that the fo	oregoing) is true and correct		<u> </u>					

Title

Supervisor

PETROLEUM ENGINEER