


Mike,

As you can see from our report the morrow could not buck the line pressure and the Natural Gas Pipeline Co's compressor wasn't operable so the Morrow was not produced. However we have a good test because the slow building Morrow is still building from the last time it was produced while the compressor was working. It did continue to build while the Atoka was producing and really drawing down.

Thank you
John W West

HORIZON

**OIL & GAS CO.
OF TEXAS** (a corporation)



P. O. BOX 7

SPEARMAN, TEXAS 79081

October 18, 1977

705-659-2544
659-3270

West Engineering Company
412 North Dal Paso
Hobbs, New Mexico 88240

Gentlemen:

Attached please find copy of letter from Oil Conservation Commission about the Packer Leakage Test on our State 28-2 lease in Eddy County, New Mexico. Would you please run these tests as soon as possible and forward the results to the Oil Conservation Commission. We also need copies of these tests mailed to our Spearman office.

Yours very truly,

HORIZON OIL & GAS CO. OF TEXAS

Everett R. Tracy
Production Manager



ERT:fw

file

cc: Oil Conservation Commission, Artesia, N.M.

RECEIVED

NOV 2 1977

O. C. C.
ARTESIA, OFFICE