OCD-Artesia

0154

FORM APPROVED UNITED STATES Form 3160-5 Budget Bureau No. 1004-0135 (June 1990) DEPARTMENT OF THE INTERIOR Expires: March 31, 1993 **BUREAU OF LAND MANAGEMENT** 5. Lease Designation and Serial No. LC-029548-A SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE FECTIVEL I. Type of Well Oil Gas Well Well 667 1 6 **19**93 8. Well Name and No. C.A. RUSSELL #11 2. Name of Operator C. L. D 9. API Well No. SOCORRO PETROLEUM COMPANY 3. Address and Telephone No. 10. Field and Pool, or Exploratory Area P.O. BOX 38, LOCO HILLS, NM 88255

4 Location of Well (Footage, Sec., T., R., M., or Survey Description) GRAYBURG JACKSON 11. County or Parish, State 2350 1000 990' FNL & 2250' FWL, SEC 18, T17S, R31E EDDY, NEW MEXICO CHECK APPROPRIATE BOX(8) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Change of Plans Notice of Intent Abandonment **New Construction** Recompletion Non-Routine Practuring Subsequent Report Plugging Back Water Shut-Off Conversion to Injection Final Abandonment Notice **Altering Casing** Other PUT WELL ON PRODUCTION L Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) 13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled. give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* To pull and inspect tubing, rods and pump. Clean all fill from wellbore. Perform a acid clean up. Run tubing, rods and pump and place well back on production. Plan to commence on the 1st half of November 1993. OPERATIONS SUPERINTENDENT PETROLEUM ENGINEER (DRIG SCD.) IDE G. LARA