5. LEASE

Form 9-331 Dec. 1973

11 0051a, TH 83210

Form Approved. Budget Bureau No. 42-R1424

· Papaga

UNITED STATES

DEPARTMENT OF THE INTERIOR	NM 2747	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR T	R BE NAME
	• 1	RECEIVED E
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME	JUL 26 1982
reservoir, Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME	A Section of the sect
1. oil gas	Jackson B 🗸 🔅 🖟	O. C. D.
well well other Water Injector	9. WELL NO.	ARFESIA, OFFICE
2. NAME OF OPERATOR	<u>30 % 🗒 🖟 🖔 🥫 </u>	92 F 6
Burnett Oil Co., Inc.	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR	Square Lake	[장수형
1500 InterFirst Tower, Ft. Worth, TX 76102	11. SEC., T., R., M., OR BLK. A	ND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA 1-17S-30E	
AT SURFACE:660' FSL, 1980' FWL	12. COUNTY OR PARISH 13.	STATE
AT TOP PROD. INTERVAL:	Eddy	NM
AT TOTAL DEPTH:	14. API NO.	10 to
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,		, čįta
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, I	(DB: AND WD)
	3717'DF	1 d d d
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	2.514	3 2 2 3
TEST WATER SHUT-OFF	0 Last 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
FRACTURE TREAT	to foi seme vento:	: 8 a a a a a a a a a a a a a a a a a a
SHOOT OR ACIDIZE		**
PULL OR ALTER CASING	(NOTE: Report results of multiple of change on Form 9–330.) ్ర క్రామాన్ చెప్పార్లు	completion or zone
MULTIPLE COMPLETE		actions operations secepted be number intering troom.
CHANGE ZONES		7 6 7 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6
ABANDON*	nsiem Juoris eb dae ed dae orden d bas	enoidounten enoidounde (lew oldened on the streens on the formun ent be
(other)	ा किया मुख्या कार्यक्रम उ	. State
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinen	irectionally drilled, give subsurfac	pertinent dates,
As per approval of NMOCD, the following remed	ial work was performed	to isolate
the salt section from the surface:	en de la composition de la com	전 6 2 분 전 7 2 분
C/7/0/ B 1		
6/7/84 Found top of cement @1504'	0 1 5 6 6 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	
7/5/84 Ran 4½" OD retrievable bridge plug, s		
Tested okay to 1500 psi. Perforated		
down 4½" casing w/ 100 sx Class C, 2%	Caci, e 3 BPM e-300-7	00 psi Full
returns out 8-5/8" casing. Displaced		្តបំពុំ បំពុំព្រះ - រុះ (ពី ក្រៀប!!
7/6/84 Ran radioactive tracer survey down 4½		
to be sound; all fluids going out bot		
8-5/8" casing with 85 sx Halliburton 1		
CaCl @ 3 BPM @ 500 psi. Left 8-5/8"		
7/9/84 Drilled out cement from 4½". Pulled ro		
7/10/84 Ran $4\frac{1}{2}$ " tension packer on 93 jts. 2-3 2840'. Packed off, resumed injection		g. and set @
18. Thereby certify that the foregoing is true and correct	. ලදුල් දිදුල් දිදුල් දිදුල් දිදුල්	
John C Mc Star & Prod Sunt	7/16/10/24 33	6 등 기표
(/ နေကတ္တည်းလေနကို ခဲ့ခဲ့ကိုကိုကို ကို	安全基金 보기	- 5934
(This space for Federal or State offi	ice use) ဆီမီတို့ရာမှ စီရှိ	1 6 2
Strait (1)	프랑크보다 등급	ta bar
APPROVED BY TITLE TOTALL CONDITIONS OF APPROVALLE ANY 1004	DATE Source State	<u> </u>
100 1004	를 받는 것은 등록	有異年叢
(1000)	취출회원 기원	