

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-015-21908

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
E-537-5

MAR 23 1992

O. C. D.
N.M.S.A. OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Empire South Deep Unit
2. Name of Operator Amoco Production Company	8. Well No. 11
3. Address of Operator P. O. Box 3092, Houston, TX 77253 Rm. 17.182	9. Pool name or Wildcat
4. Well Location Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>2130</u> Feet From The <u>West</u> Line Section <u>32</u> Township <u>17-S</u> Range <u>29-E</u> NMPM <u>Eddy</u> County	10. Elevation (Show whether DP, RKB, RT, GR, etc.) 3609' RDB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rig up service unit.
POH tbg.
Perform cmt squeeze on casing leak as per cmt brief attached.
WOC. Test to 500 psi for 30 min.
Spot 100' cmt plug at 2867'-2967'.
Spot 10' cmt plug at surface.
Install P&A marker. Cut off wellhead.
Rig down.

P&A Changes AS per our attached sheet

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kim A. Colvin TITLE Asst. Admin. Analyst DATE 3/17/92
TYPE OR PRINT NAME Kim A. Colvin TELEPHONE NO. 713/ 596-7686

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE 5/4/92
CONDITIONS OF APPROVAL, IF ANY: