

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Artesia, NM 88210

CATE
NO. (re-)

Form approved.
Budget Bureau No. 1004-1135
Expires August 31, 1985

ckf

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
TEXACO Producing, Inc.

3. ADDRESS OF OPERATOR
P. O. Box 728, Hobbs, New Mex. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
Unit Letter ^E H, 1980' FNL and 560' FWL

14. PERMIT NO. 30-015 22259 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
GL 3819' KB 3829'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 11-11-85 MIRU pulling unit. Pull rods and tbg. Install BOP. Ran bit and scraper to PBTD 2350'.
- 11-12-85 Circ hole w/ 2% KCL Water. Pull bit and scraper. Run 5½" pkr. w/ 184' of tailpipe. Spot 335 gals scale converter across 7-Rivers perfs 2202'-2326'. Set pkr. @ 2158'. SION.
- 11-13-85 Raised and set pkr. @ 2005'. Acidized 7-Rivers perfs w/ 3,000 gals 15% NEFE acid and 48 balls. No ball out. Swab back.
- 11-14-85 Swab. Pull tbg. and pkr. Run 2 3/8" tbg, rods and pump. Place on production. Rig down pulling unit.

18. I hereby certify that the foregoing is true and correct

SIGNED W.B. Clark

TITLE Dist. Opr. Mgr.

DATE 12-5-85

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

Title 18 U.S.C. Sec. 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.