

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRICATE*

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

ARTESIA, OFFICE

5. LEASE DESIGNATION AND SERIAL NO.

LC 030570 B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Power Federal Com.

9. WELL NO.

1-Y

10. FIELD AND POOL, OR WILDCAT

Cedar Lake Morrow

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

26 - 17S - 30E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3590.4' GL

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Plug back while re-completing X
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROMISED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Page 2

13. WIH with RBP and pkr; acidized perfs with 1300 gals 15 HCL acid; swab-tested well. Found non-productive; TOH.
14. Set CIBP @ 7904' and dumped 35' cement on top (this plug covers Wolfcamp formation top).
15. Perforated 3rd Bone Springs formation from 7694-7704, 7730-34 and 7744-50 @ 1 SPF; total holes = 23.
16. TIH with RBP and pkr; acidized with 1500 gals 15% HCL acid; swab-tested zone; found non-productive; TOH.
17. Set CIBP @ 7670' and dumped 35' cement on top (this plug covers 3rd Bone Springs formation top). Set CIBP @ 5624' (this plug is to protect holes in casing from treatment of upper sone).
18. Perforated Glorietta formation from 5386-90, 5406-10 & 5419-24 @ 1 SPF; total holes = 17.
19. TIH with pkr; set pkr @ 5316'. Acidized with 850 gals 15% HCL acid; swab-tested zone; found non-productive.
20. Shut well in and rigged down pulling unit.

Note: Copy of T* Survey attached.

Will file notice of intent to P & A.

18. I hereby certify that the foregoing is true and correct

SIGNED M. B. Brumwell

TITLE Field Foreman

DATE Sept. 20, 1985

(This space for Federal or State office use)

APPROVED/ACCEPTED FOR RECORD
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

OCT 1 1985

*See Instructions on Reverse Side