

OIL CONSERVATION DIVISION

P. O. BOX 2048

SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-2130	

RECEIVED BY

JUN 13 1984

O. C. D.
ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFEINER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM O-101) FOR PLUG BACK TO A DIFFERENT RESERVOIR.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name Burnham Grayburg San Andres Unit
2. Name of Operator Anadarko Production Company	8. Farm or Lease Name Tract 6
3. Address of Operator P. O. Drawer 130, Artesia, New Mexico 88210	9. Well No. 4
4. Location of Well UNIT LETTER N 1310 FEET FROM THE South LINE AND 2630 FEET FROM West LINE, SECTION 2 TOWNSHIP 17S RANGE 30E NMPM.	10. Field and Pool, or Wildcat Square Lake-Grayburg-SA
11. Elevation (Show whether DF, RT, GR, etc.) 3749.6' GL	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		Completion <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up pulling unit.
2. Perforated Lovington Zone from 3176-3178 and 3183-3186; total holes = 11 with .40" diam.
3. Acidized Lovington perfs with 1000 gals 15% Acid and fraced with 12,000 gals X-linked gel, 5500# 20/40 sand and 9500# 10/20 sand.
4. Set RBP above Lovington perfs.
5. Perforated Grayburg Zone @ 2928,30,31,32,34,47,62,64,66, 3034,36 and 38; total holes = 12 with .38" diam.
6. Acidized Grayburg perfs with 1100 gals 15% Acid and fraced with 25,000 gals X-linked gel, 5500# 20/40 sand & 20,000# 10/20 sand.
7. Washed out sand; retrieved RBP; washed out sand from Lovington frac to 3244'.
8. Ran tubing and rods with bottomhole pump.
9. Installed production equipment and placed on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Brunwell TITLE Field Foreman DATE June 11, 1984

Original Signed By
Leslie A. Clements
Supervisor District #

APPROVED BY _____ TITLE _____ DATE JUN 18 1984

CONDITIONS OF APPROVAL, IF ANY: