

RECEIVED BY DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

JUL 2 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ARTESIA, OFFICE

WELL ☒ WELL ☐ OTHER ☐

2. NAME OF OPERATOR

JFG ENTERPRISE

3. ADDRESS OF OPERATOR

P.O. Box 100, Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

990' FNL & 660' FEL of Sec. 21-T17S-R30E

(Unit A)

(NE/4 NE/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, RT, GR, etc.)

3663' G.L.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0467932

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Brown Crow Fed

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Grayburg-Jackson

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 21-T17S-R30E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Drill out DV Tools

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-28-85 Drilled out DV Tools

5-29-85 Ran Bond Logs

5-29-85 Ran Comp/ Nuutron/Gamma Ray Log

5-30-85 Perforated 3484'-3491'-3492'-3494'-3496'-3498'-3500'-3502'-3504'-
3506'-3508'-3510' (12 holes)
Treated with 500 gal. 15% NE FE Acid.
Perforated (3265'-3266'-3267'-3269') (3288'-3292'-3293'-3295')
(3309'-3310'-3312'-3316'-3318'-3320'-3322'-3324'-3326')
(3370'-3371'-3372'-3373'-3374')

Treated with 2000 gal acid.

5-31-85 Swabbing back at rate of 12 B.O.P.D. No water.
Preparing to frac.

ACCEPTED FOR RECORD

JUL 1 1985

CAPISBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Partner

DATE

6-1-85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: