

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN Llicate
(Other instructions on re-
vise)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM-0467932

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

ARTESIA, OFFICE

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

JFG Enterprise

3. ADDRESS OF OPERATOR

P.O. Box 100, Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

330' FSL & 660' FEL Sec. 21, T-17S, R-30E,
Eddy County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3624.5

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Brown Crow

9. WELL NO.

#2

10. FIELD AND POOL, OR WILDCAT

Grayburg-Jackson-SR-6

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

330' FSL & 660' FEL

Sec. 21, T-17S, R-30E

12. COUNTY OR PARISH

Eddy

13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

9-30-85

Move in P.U. R.U. Perf 3246'-3254' 9 holes; Perf 3031'-3036- 6 Holes;
3051'-3056'- 6 holes; Perf 2944'-2946'- 4 holes; 2935'-2938'- 4 holes;
Perf 2817'-2820'- 4 holes; Perf 2827'-2830'-3 holes; Perf. 2579'-2590'-
12 holes; 49 holes Total.

10-1-85

Acidize with 750 acid 3246-3254. No shows tight. Acidize with 750
gal. Zone 3031 to 3056. Show gas & oil; Acidize Zone 2935-2946
with 750 gal. Acid. Good show gas and oil.

10-2-85

Acidize Zone 2817-to 2830' with 750 gal Acid. Small show of oil
and gas.
Acidize Zone 2579 to 2590 with 750 gal. Acid.
Small show of gas and oil.
Prepare to Frac.

18. I hereby certify that the foregoing is true and correct

SIGNED

J. J. Fletcher

TITLE

Agent

DATE

10-21-85

(This space for Federal or State office use)

APPROVED BY

ACCEPTED FOR RECORD

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

OCT 23 1985

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO