

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

(Other instructions on form 100)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different formation.
Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

1. NAME OF OPERATOR

Siete Oil & Gas Corporation

2. ADDRESS OF OPERATOR

P.O. Box 2523

Roswell, New Mexico 88202

3. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980'FNL & 330'FWL

Unit Letter E

APR 11 '88

14. FORMER NO.

API No. 30-015-25439

15. ELEVATIONS (Show whether SP, ST, OR, etc.)

3696' GR

ARTESIA, OFFICE

4/5F
1. NAME OF OPERATOR AND SERIAL NO.
NM-43727

2. NAME OF WELL, ALLOTTED OR OTHER NAME

3. DATE OF REPORT

4. NAME OF LEASE

Falcon Federal

5. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Square Lake-Grayburg-S.A.

11. SEC. T. R. M. OR B.L. AND QUARTER OR AREA

Sec. 5: T17S R30E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

FILL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and space pertinent to this work.)

1. Set cast iron bridge plug @ 2885'
2. Set 35' cement plug on CIBP
3. Set cast iron bridge plug @ 2625'
4. Set 35' cement plug on CIBP
5. Set 100' plug from 1061' to 961'
6. Set 100 cement plug from 300' to 400' across 8 5/8" shoe
7. Set 50' cement plug @ surface
10# gallon salt get mud to be used between plugs
8. Set 4' marker with legal description, weld on @ surface

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE V.P. Drilling & Production

DATE March 25, 1988

(This space for Federal or State office use)

APPROVED BY [Signature]

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

APR 6 1988

Approved by _____
Special Agent in Charge

*See Instructions on Reverse Side

POST 10-2
4-1-88
P & A
CARLSBAD, NEW MEXICO