

Procedure cont. West Indian Basin #2
Water shut-off and re-perf Upper Penn

7. FLOW WELL THROUGH TEST METER TO FRAC TANK. REPORT RESULTS TO REGION OFFICE. RD MO
WS RIG.
8. CONTACT ENGINEERING FOR STIMULATION DESIGN, IF NECESSARY.